

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005610/UEA3Q2**Date:** 06/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100433958
Claimant Vehicle No :	SMW1171H	Insured Vehicle No :	GBE2902J
Date of Loss:	13/06/2022	Nature of Claim:	TP
		Claim No:	8423746205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1171H	Engine No:	2NR5458264
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3701211415
Reg. Date:	03/11/2020 (Man. Year: 2020)	Odometer:	29488 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,344.25	4,311.07	3,033.18	41.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	2,320.00	950.00	29.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,614.25	6,631.07	3,983.18	37.53
+ GST 7.00/7.00% (S\$)	743.00	464.17	278.83	37.53
Nett Amount (S\$)	11,357.25	7,095.24	4,262.01	37.53
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,797.24		

INSPECTION

Date of Assignment:	14/06/2022		
Date Inspected:	14/06/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	557.70 FL	*557.70 FL
2	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	199.60 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	353.00 FL	*353.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Cracked	328.60 FL	*328.60 FL
6	1		*BOOTLID	Dented	838.90 FL	*838.90 FL
7	1		*BOOTLID LOCK	Twisted	423.90 FL	*423.90 FL
8	1		*BOOTLID KEYLESS SENSOR	Cracked	76.30 FL	*76.30 FL
9	1		*BOOTLID LOGO	Necessary	50.70 FL	*50.70 FL
10	1		*BOOTLID VIOS BADGE	Necessary	58.60 FL	*58.60 FL
11	1		*BOOTLID E BADGE	Necessary	47.60 FL	*47.60 FL
12	1		*BOOTLID KEYLESS SWITCH	Not Necessary	105.20 FL	*- FL
13	1		*BOOTLID NUMBER PLATE LAMP	Not Necessary	69.00 FL	*- FL
14	1		*BOOTLID NUMBER PLATE LAMP GARNISH	Twisted	85.20 FL	*85.20 FL
15	1		*BOOTLID WEATHERSTRIP	Twisted	186.50 FL	*186.50 FL
16	2		*BOOTLID REFLECTOR	Cracked	494.40 FL	*494.40 FL
17	1		*BOOTLID INNER TRIM BOARD	Not Necessary	344.90 FL	*- FL
18	12		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	129.60 FL	*- FL
19	2		*BOOTLID HINGE	Repair	170.00 FL	*- FL
20	2		*TAILLAMP	Cracked	765.80 FL	*765.80 FL
21	2		*TAILLAMP CLIPS	Not Necessary	13.60 FL	*- FL
22	1		*TAILLAMP PANEL N/S	Repair	128.20 FL	*- FL
23	1		*REAR END PANEL	Badly Dented	789.30 FL	*789.30 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	295.60 FL	*295.60 FL
25	2		*REAR FENDER (NPA)	Repair	0.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	698.60 FL	*- FL
27	12		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	129.60 FL	*- FL
28	1		*FLOOR PANEL	Repair	739.90 FL	*- FL
29	1		*FLOOR PANEL FLOOR BOARD	Not Necessary	317.30 FL	*- FL
30	1		*TOOLS COMPARTMENT FOAM TYPE	Not Necessary	105.40 FL	*- FL
31	1		*TAILLAMP LOWER BRACKET	Cracked	21.00 FL	*21.00 FL
32	1		*SET REAR BUMPER PARKING SENSOR	Shorted	350.00 FS	*200.00 FS
33	1		*BOOTLID REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
34	1		*REAR WINDSCREEN PRIMER	Not Necessary	80.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,489.00	5,668.10
- List Item Discount on L Items 25.00/25.00% (\$)	2,144.75	1,357.03
Total Parts (\$)	7,344.25	4,311.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	300.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	100.00	80.00
3	TO DROP PETROL TANK ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHEKCING AND TESTING	New	80.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	30.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	70.00	50.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	0.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,300.00	1,000.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	1,100.00
Gross Labour Cost (\$\$)			3,270.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >