

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005612/APA3Q2**Date:** 08/06/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNB9638A**Insured Vehicle No :** SDP4555H

Date of Loss: 05/06/2022

Nature of Claim: TP

Claim No: 1920179819SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNB9638A**

Make & Model: AUDI A6, 2.0 TFSI (A)

Engine No: DKY015537

Reg. Date: 23/09/2021 (Man. Year: 2021)

Chassis No: WAUZZZF26MN076080

Colour: White

Odometer: 13357 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,505.00	12,241.76	12,263.24	50.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,212.00	7,132.00	4,080.00	36.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,717.00	19,373.76	16,343.24	45.76
+ GST 7.00/7.00% (S\$)	2,500.19	1,356.16	1,144.03	45.76
Nett Amount (S\$)	38,217.19	20,729.92	17,487.27	45.76
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Medical Costs (S\$)		33.15		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		21,765.07		

INSPECTION

Date of Assignment: 14/06/2022

Date Inspected: 14/06/2022

Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	3,012.00 FS	*2,409.60 FS
2	1		*REAR BUMPER TELEPHONE AERIAL - LH / RH	N/S Damaged	182.00 FS	*72.72 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	247.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	985.00 FS	*787.60 FS
5	1		*REAR BUMPER CHROME TRIM - LH	Not Necessary	273.00 FS	*- FS
6	1		*REAR BUMPER CHROME TRIM - CENTER	Necessary	194.00 FS	*154.80 FS
7	1		*REAR BUMPER SECURING STRIP	Damaged	193.00 FS	*154.00 FS
8	1		*BOOTLID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
9	1		*TAILGATE SENSOR LINE	Not Necessary	228.00 FS	*- FS
10	1		*CABLE TIE TERMINAL SOCKET	Not Necessary	3.00 FS	*- FS
11	1		*AERIAL FOR KESSY	Not Necessary	120.00 FS	*- FS
12	2		*REAR LIGHT REFLECTOR - INNER / OUTER LH	Not Necessary	80.00 FS	*- FS
13	1		*TAIL LIGHT - LH INNER	Cracked	1,401.00 FS	*1,120.80 FS
14	1		*TAIL LIGHT TRIM - LH INNER	Cut	49.00 FS	*39.20 FS
15	1		*TAIL LIGHT - LH OUTER	Cut	1,401.00 FS	*1,120.80 FS
16	1		*TAIL LIGHT TRIM - LH OUTER	Cut	34.00 FS	*26.48 FS
17	1		*TAIL LIGHT CLUSTER CHROME - LH	Necessary	54.00 FS	*42.80 FS
18	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	1,076.00 FS	*860.80 FS
19	2		*REAR BUMPER SEAL - LH / RH	Necessary	32.00 FS	*25.60 FS
20	2		*REAR BUMPER GUIDE SECTION - LH / RH LOWER	Not Necessary	142.00 FS	*- FS
21	2		*REAR BUMPER GUIDE SECTION - LH / RH UPPER	Not Necessary	102.00 FS	*- FS
22	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	29.00 FS	*- FS
23	1		*REAR BUMPER HOLDING STRAP - CENTER	Necessary	133.00 FS	*106.00 FS
24	1		*REAR BUMPER GUIDE PROFILE - LH	Necessary	75.00 FS	*59.36 FS
25	1		*REAR BUMPER GUIDE SECTION - CENTER	Cracked	119.00 FS	*94.80 FS
26	3		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
27	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*SET REAR BUMPER WIRING	Not Necessary	544.00 FS	*- FS
29	1		*REAR LID	Dented	4,142.00 FS	*3,313.60 FS
30	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
31	2		*REAR LID HINGE - LH / RH	Not Necessary	510.00 FS	*- FS
32	1		*REAR LID ATTACHMENT PARTS	Not Necessary	185.00 FS	*- FS
33	1		*REAR LID LOCK ACTUATOR	Not Necessary	1,414.00 FS	*- FS
34	1		*REAR LID LOCK	Not Necessary	292.00 FS	*- FS
35	1		*REAR LID LOCK FLAP COVER CAP	Not Necessary	8.00 FS	*- FS
36	1		*REAR LID LOCK STRIKER	Not Necessary	37.00 FS	*- FS
37	1		*REAR LID FLAP GASKET	Not Necessary	266.00 FS	*- FS
38	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
39	1		*A6 EMBLEM	Necessary	104.00 FS	*82.80 FS
40	1		*TAILGATE CHROME TRIM STRIP - CENTER	Necessary	391.00 FS	*312.80 FS
41	1		*REAR END PANEL	Dented	560.00 FS	*448.00 FS
42	1		*REAR END PANEL REINFORCEMENT	Repair	1,128.00 FS	*- FS
43	1		*REAR END PANEL TRIM	Not Necessary	310.00 FS	*- FS
44	1		*REAR SILENCER INTERMEDIATE	Not Necessary	2,260.00 FS	*- FS
45	1		*DUAL CLIP	Not Necessary	68.00 FS	*- FS
46	1		*CENTER SILENCER HEAT SHELF	Not Necessary	155.00 FS	*- FS
47	1		*REAR SILENCER HEAT SHIELD - LH	Not Necessary	98.00 FS	*- FS
48	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
49	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
50	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
51	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
52	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
53	1		*SUNDRIES	Necessary	400.00 FS	*97.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 24,505.00 12,241.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,500.00
4	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND REAR END PANELLING	New	3,500.00	2,200.00
5	TO RENEW REAR EXHAUST SILENCER AND ALIGN INTO POSITION	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
Gross Labour Cost (\$\$)			11,212.00	7,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >