

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22005616/KVCM4**Date:** 22/09/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962396
Claimant Vehicle No :	GBB6220H	Insured Vehicle No :	SMA8214M
Date of Loss:	10/06/2022	Nature of Claim:	TP
		Claim No:	276481

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB6220H	Engine No:	D4CB9518866
Make & Model:	HYUNDAI H-1 STAREX, 2.5 D CRDi (A)	Chassis No:	KMFWBH7JR9U169865
Reg. Date:	26/08/2009 (Man. Year: 2009)	Odometer:	242147 km
Colour:	Silver		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/70 R16	Rear Tyre Size:	215/70 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,058.58	2,687.20	6,371.38	70.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,430.00	2,070.00	59.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,558.58	4,117.20	8,441.38	67.22
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	12,558.58	3,300.00	9,258.58	73.72
+ GST 7.00/7.00% (S\$)	879.10	231.00	648.10	73.72
Nett Amount (S\$)	13,437.68	3,531.00	9,906.68	73.72

INSPECTION

Date of Assignment:	14/06/2022	
Date Inspected:	14/06/2022	Inspected At: H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Sep 2022)	
Parts:	N/A	HYUNDAI H-1 STAREX 2.5 D CRDi (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB6220H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Repair	2,620.40 FL	*- FL
2	1		*TAIL GATE WEATHER STRIP	Serviceable	136.00 FL	*- FL
3	2		*TAIL GATE HINGE 1 @ 120.00	Repair	240.00 FL	*- FL
4	2		*TAIL GATE DAMPER 1 @ 93.40	Serviceable	186.80 FL	*- FL
5	1		*TAIL GATE INNER TRIM BOARD	Serviceable	297.20 FL	*- FL
6	1		*TAIL GATE INNER LOCK	Repair	84.00 FL	*- FL
7	1		*REAR BUMPER	Bent	468.60 FL	*468.60 FL
8	10		*REAR BUMPER CLIPS 1 @ 3.00	Necessary	30.00 FL	*30.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	347.00 FL	*347.00 FL
10	1		*O/S REAR BUMPER TOP GARNISH	Serviceable	158.00 FL	*- FL
11	2		*REAR BUMPER BRACKET 1 @ 22.00	Repair	44.00 FL	*- FL
12	1		*REAR BUMPER SPONGE	Cracked	74.30 FL	*74.30 FL
13	1		*O/S REAR BUMPER SIDE RETAINER	O/s Cracked	22.00 FL	*22.00 FL
14	1		*O/S REAR BUMPER SIDE RETAINER -- 2	Necessary	22.00 FL	*22.00 FL
15	1		*O/S REAR BUMPER SIDE COVER	Missing	95.30 FL	*95.30 FL
16	1		*O/S REAR BUMPER MUDFLAT	Cracked	22.00 FL	*22.00 FL
17	1		*O/S REAR FENDER	Bent/Buckled	1,640.20 FL	*1,451.60 FL
18	1		*O/S REAR FENDER INNER PANEL	Repair	980.20 FL	*- FL
19	1		*O/S REAR FENDER AIR DUCT	No such part	133.10 FL	*- FL
20	1		*O/S REAR FENDER INNER GARNISH	Serviceable	611.20 FL	*- FL
21	2		*TAIL LAMP 1 @ 385.00	N/s Cracked/ O/s Cracked	770.00 FL	*770.00 FL
22	1		*O/S TAIL LAMP PANEL	Repair	233.00 FL	*- FL
23	1		*REAR END PANEL	Repair	270.10 FL	*- FL
24	1		*REAR NUMBER PLATE LAMP	Serviceable	26.00 FL	*- FL
25	1		*REAR HYUNDAI STICKER	Not Necessary	30.20 FL	*- FL
26	1		*REAR H1 STICKER	Not Necessary	26.30 FL	*- FL
27	1		*REAR HYUNDAI LOGO	Necessary	26.20 FL	*26.20 FL
28	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
29	1		*REAR WINDSCREEN GLASS INNER GUM	Not Necessary	60.00 FS	*- FS
30	1		*SET REAR BUMPER SENSOR	Serviceable	350.00 FS	*- FS
31	1		*O/S REAR WHEEL RIM	Serviceable	398.30 FS	*- FS
32	1		*O/S REAR WHEEL TYRE	Serviceable	385.00 FS	*- FS
33	1		*REAR 70KM/H STICKER	Necessary	50.00 FS	*12.00 FS
34	1		*SET REAR 8 PAX STICKER	Necessary	50.00 FS	*12.00 FS
35	1		*REAR NO. PLATE	Serviceable	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,977.40	3,353.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,918.82	665.80
Total Parts (\$\$)	9,058.58	2,687.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	1,600.00	700.00
2	TO PUTTY AND SPRAY PAINTING	New	1,200.00	550.00
3	RE-SEAL ANTI RUST	New	200.00	30.00
4	TO CHECK WIRING	New	120.00	20.00
5	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR	New	120.00	50.00
7	REMOVE AND REFIX UPHOLSTERY,CUSHION SEAT,GARNISH CARPET ETC	New	180.00	80.00
Gross Labour Cost (\$)			3,500.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >