



簡福星嘢嘢工廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221468-00E
GST Reg. No. M9-0005333-EINSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001401006	Date of Loss:	12/06/2022
Vehicle Reg. No.:	SKS778J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THIAM SENG QIAN LEWIS BENEDICT		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	12/10/2010
Vehicle Colour:	METALLIC PEARL WHITE		
Engine No:	27186030059890	Chassis No:	WDD2073472F046588
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	12,600.50
Miscellaneous Items	40.00
Labour	920.00
Paintwork Labour	1,100.00
Towing	0.00
Calculated Gross Total (\$\$)	14,660.50
- Excess (\$\$)	600.00
(\$\$)	14,060.50
+ GST 7.00% (\$\$)	984.24
Nett Amount (\$\$)	15,044.74

This claim is handled by: **MT TAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 13 Jun 2022)

Parts: 143 **MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET Distorted	0.00	0.00	*1,585.00 F ✓
2	1		*FRONT BONNET CHROME could	0.00	0.00	*76.00 F ✓
3	1		*FRONT BONNET LOCK Dented	0.00	0.00	*65.00 F ✓
4	1		*FRONT BONNET LOCK LOWER RH given	0.00	0.00	*45.00 F ✓
5	1		*FRONT BONNET LOCK LOWER LH	0.00	0.00	*45.00 F ✓
6	1		*FRONT BONNET EMBLEM new	0.00	0.00	*40.00 F ✓
7	1		*FRONT BONNET STOPPER RH given	0.00	0.00	*18.00 F ✓
8	1		*FRONT BONNET STOPPER LH	0.00	0.00	*18.00 F ✓
9	1		*FRONT TOP PANEL Reps	0.00	0.00	*110.00 F ✓
10	1		*FRONT TOP PANEL GARNISH could	0.00	0.00	*75.00 F ✓
11	1		*FRONT BRACE PANEL Dented	0.00	0.00	*25.00 F ✓
12	1		*FRONT HEADLAMP PANEL RH given	0.00	0.00	*155.00 F ✓
13	1		*FRONT HEADLAMP PANEL LH	0.00	0.00	*155.00 F ✓
14	1		*FRONT HEADLAMP RH crushed	0.00	0.00	*1,720.00 F ✓
15	1		*FRONT HEADLAMP LH smashed	0.00	0.00	*1,720.00 F ✓
16	1		*FRONT GRILLE smashed	0.00	0.00	*470.00 F ✓
17	1		*FRONT GRILLE GARNISH Dented	0.00	0.00	*110.00 F ✓
18	1		*FRONT GRILLE EMBLEM 3 smashed	0.00	0.00	*95.00 F ✓
19	1		*FRONT GRILLE EMBLEM BASE	0.00	0.00	*45.00 F ✓
20	1		*FRONT FENDER LH 2 crushed	0.00	0.00	*525.00 F ✓
21	1		*FRONT FENDER SHIELD LH given	0.00	0.00	*95.00 F ✓
22	10		*FRONT FENDER SHIELD CLIP	0.00	0.00	*30.00 F ✓
23	1		*FRONT BUMPER Distorted	0.00	0.00	*990.00 F ✓
24	1		*FRONT BUMPER FOAM could	0.00	0.00	*95.00 F ✓
25	1		*FRONT BUMPER REINFORCEMENT Best	0.00	0.00	*175.00 F ✓
26	1		*FRONT BUMPER REINFORCEMENT BRACKET RH ?	0.00	0.00	*160.00 F ?
27	1		*FRONT BUMPER REINFORCEMENT BRACKET LH ?	0.00	0.00	*160.00 F ?
28	1		*FRONT BUMPER LOWER GRILLE crushed	0.00	0.00	*65.00 F ✓
29	1		*FRONT BUMPER SENSOR Dented	0.00	0.00	*153.00 F ✓
30	4		*FRONT BUMPER SENSOR COVER ?	0.00	0.00	*200.00 F ?
31	1		*FRONT BUMPER FOGLAMP COVER LH new	0.00	0.00	*50.00 F ✓
32	1		*FRONT BUMPER CARRIER CENTRE ?	0.00	0.00	*150.00 F ?
33	1		*FRONT BUMPER CARRIER LH ?	0.00	0.00	*15.00 F ?
34	1		*FRONT BUMPER WIPER COVER LH Missing	0.00	0.00	*40.00 F ✓
35	1		*FRONT BUMPER WIPER HOSE new	0.00	0.00	*85.00 F ✓
36	1		*AIR BUFLER TOP ?	0.00	0.00	*110.00 F ?
37	1		*AIR BUFLER LOWER ?	0.00	0.00	*95.00 F ?
38	1		*AIR CON CONDENSER Dented	0.00	0.00	*720.00 F ✓
39	1		*RADIATOR ?	0.00	0.00	*445.00 F ?
40	1		*POWER STEERING PIPE	0.00	0.00	*175.00 F ?
41	1		*INTERCOOLER GARNISH ?	0.00	0.00	*265.00 F ?
42	1		*FRONT NUMBER PLATE GARNISH could	0.00	0.00	*85.00 F ✓

F=Franchise part.

Sub Total (S\$)

11,455.00

+ Margin on L,N Items 10.00% (S\$)

1,145.50

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (\$\$)						12,600.50

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE <i>cracked</i>	40.00 ✓
Sub Total (\$\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	1,100.00 800
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	40.00 30
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	100.00 ✓
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	780.00 700
Gross Labour Cost (\$\$)			2,020.00

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
P/P 14/06/22. 08 days.
Not Authorized.
Exem: To be advised.
96893735.