

Repairer Estimates

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 13 Jun 2022)

Parts: 143

MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET Distorted	0.00	0.00	*1,585.00 F ✓
2	1		*FRONT BONNET CHROME } Not Nec	0.00	0.00	*76.00 F ✓
3	1		*FRONT BONNET LOCK	0.00	0.00	*65.00 F ✓
4	1		*FRONT BONNET LOCK LOWER RH } from	0.00	0.00	*45.00 F ✓
5	1		*FRONT BONNET LOCK LOWER LH	0.00	0.00	*45.00 F ✓
6	1		*FRONT BONNET EMBLEM xlu	0.00	0.00	*40.00 F ✓
7	1		*FRONT BONNET STOPPER RH } from	0.00	0.00	*18.00 F ✓
8	1		*FRONT BONNET STOPPER LH	0.00	0.00	*18.00 F ✓
9	1		*FRONT TOP PANEL Reps	0.00	0.00	*110.00 F ✓
10	1		*FRONT TOP PANEL GARNISH Cracked	0.00	0.00	*75.00 F ✓
11	1		*FRONT BRACE PANEL Dant.	0.00	0.00	*25.00 F ✓
12	1		*FRONT HEADLAMP PANEL RH nrm	0.00	0.00	*155.00 F ✓
13	1		*FRONT HEADLAMP PANEL LH - LH Best.	0.00	0.00	*155.00 F ✓
14	1		*FRONT HEADLAMP RH Cracked	0.00	0.00	*1,720.00 F ✓
15	1		*FRONT HEADLAMP LH smashed	0.00	0.00	*1,720.00 F ✓
16	1		*FRONT GRILLE smashed	0.00	0.00	*470.00 F ✓
17	1		*FRONT GRILLE Dant.	0.00	0.00	*110.00 F ✓
18	1		*FRONT GRILLE GARNISH } Not Nec	0.00	0.00	*95.00 F ✓
19	1		*FRONT GRILLE EMBLEM	0.00	0.00	*45.00 F ✓
20	1		*FRONT GRILLE EMBLEM BASE	0.00	0.00	*525.00 F ✓
21	1		*FRONT FENDER LH Behind	0.00	0.00	*95.00 F ✓
22	10		*FRONT FENDER SHIELD LH Behind	0.00	0.00	*30.00 F ✓
23	1		*FRONT FENDER SHIELD CLIP Not Nec	0.00	0.00	*990.00 F ✓
24	1		*FRONT BUMPER Distorted	0.00	0.00	*95.00 F ✓
25	1		*FRONT BUMPER FOAM Cracked	0.00	0.00	*95.00 F ✓
26	1		*FRONT BUMPER REINFORCEMENT Best	0.00	0.00	*175.00 F ✓
27	1		*FRONT BUMPER REINFORCEMENT BRACKET RH } Not Nec	0.00	0.00	*160.00 F ✓
28	1		*FRONT BUMPER REINFORCEMENT BRACKET LH } Not Nec	0.00	0.00	*160.00 F ✓
29	1		*FRONT BUMPER LOWER GRILLE Cracked	0.00	0.00	*65.00 F ✓
30	4		*FRONT BUMPER SENSOR Dant. 2 pieces	0.00	0.00	*153.00 F ✓
31	1		*FRONT BUMPER SENSOR COVER Not Nec	0.00	0.00	*200.00 F ✓
32	1		*FRONT BUMPER FOGLAMP COVER LH Cracked	0.00	0.00	*50.00 F ✓
33	1		*FRONT BUMPER CARRIER CENTRE Not Nec	0.00	0.00	*150.00 F ✓
34	1		*FRONT BUMPER CARRIER LH Not Nec	0.00	0.00	*15.00 F ✓
35	1		*FRONT BUMPER WIPER COVER LH Missing	0.00	0.00	*40.00 F ✓
36	1		*FRONT BUMPER WIPER HOSE Not Nec	0.00	0.00	*85.00 F ✓
37	1		*AIR BUFLER TOP Behind	0.00	0.00	*110.00 F ✓
38	1		*AIR BUFLER LOWER Behind	0.00	0.00	*95.00 F ✓
39	1		*AIR CON CONDENSER Danted	0.00	0.00	*720.00 F ✓
40	1		*RADIATOR Cracked	0.00	0.00	*445.00 F ✓
41	1		*POWER STEERING PIPE Not Nec	0.00	0.00	*175.00 F ✓
42	1		*INTERCOOLER GARNISH Not Nec	0.00	0.00	*265.00 F ✓
			*FRONT NUMBER PLATE GARNISH Cracked	0.00	0.00	*85.00 F ✓

F=Franchise part

Sub Total (S\$)

11,455.00

+ Margin on L.N Items 10.00% (S\$)

1,145.50

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09 Not valid without Reference section
Generated using Merimen e-Claims IEAS

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
		<u>Miscellaneous Items</u>	40.00 ✓
1	1	FRONT NUMBER PLATE <i>Cracked</i>	
Sub Total (\$\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
	<u>Paintwork Labour</u>		
1	SPRAYPAINTING CHARGES	New	1100.00 800
	<u>Labour items</u>		
2	TO CHECK WIRING SYSTEM	New	40.00 30
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	100.00 ✓
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	780.00 700
Gross Labour Cost (\$\$)			2,020.00

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09 Not valid without Reference section
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan
P/P 14/06/22. 08 days.
Not Authorized.
Exem: To be advised.
96893735.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)
 Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:06
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER FOGLAMP LH <i>cracked</i>	0.00	0.00	*250.00 F ✓
2	1		*FRONT BUMPER SDIE RETAINER <i>new</i>	0.00	0.00	*12.00 F ✓
3	1		*BRACING (2078880190) <i>Damaged</i>	0.00	0.00	*32.00 F ✓
4	1		*RADIATOR PIN <i>new</i>	0.00	0.00	*8.00 F ✓
5	1		*RADIATOR MOUNTING <i>Damaged</i>	0.00	0.00	*16.00 F ✓
6	1		*FRONT AIR INTAKE COVER <i>Damaged</i>	0.00	0.00	*72.00 F ✓
7	1		*SAFTY HOOK <i>new</i>	0.00	0.00	*38.00 F ✓
8	1		*FRONT BONNET HINGE RH <i>new</i>	0.00	0.00	*78.00 F ✓
9	1		*FRONT BONNET HINGE LH <i>new</i>	0.00	0.00	*78.00 F ✓
10	1		*FRONT BUMPER WIPER NOZZLE COVER SPRING <i>Damaged</i>	0.00	0.00	*9.00 F ✓
11	1		*SIDE BRACKET RH <i>new</i>	0.00	0.00	*16.00 F ✓
12	1		*SIDE BRACKET LH <i>new</i>	0.00	0.00	*16.00 F ✓
13	1		*FRONT BUMPER SENSOR WIRE <i>snapped</i>	0.00	0.00	*150.00 F ✓
F=Franchise part.						
Sub Total (S\$)						775.00
+ Margin on L.N Items 10.00% (S\$)						77.50
Total Parts (S\$)						852.50

Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:06. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Adrian King
 S.S.

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
			Total Parts (S\$)			12,600.50

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09 Not valid without Reference section
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)
Parts: 143 MERCEDES-BENZ E250 1.8 CCI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:11
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*INTERCOOLER <i>Dented</i>	0.00	0.00	*620.00 F
Sub Total (S\$)						620.00
+ Margin on L,N Items 10.00% (S\$)						62.00
Total Parts (S\$)						682.00

Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Adrian Ling
sl.g.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Sep 2022)
Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SKS778J/09/09/2022 15:36
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET ABSORBER RH <i>3 paid</i>	0.00	0.00	*63.00 F ✓
2	1		*FRONT BONNET ABSORBER LH	0.00	0.00	*63.00 F ✓
3	1		*FRONT FENDER GARNISH MOULDING RH <i>cut</i>	0.00	0.00	*28.00 F ✓
4	1		*ROCKER PANEL MOULDING <i>clips</i>	0.00	0.00	*50.00 F ✓
5	1		*FRONT BUMPER WIPER COVER RH <i>new</i>	0.00	0.00	*40.00 F ✓
F=Franchise part.						
Sub Total (S\$)						244.00
+ Margin on L,N Items 10.00% (S\$)						24.40
Total Parts (S\$)						268.40

Kan Fook Sing Motor Workshop/SKS778J/09/09/2022 15:36. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DO WHEEL ALIGNMENT	New	100.00 ✓
2	HEADLAMP BLACKOUT PAINTING	New	350.00 ✓
Gross Labour Cost (\$\$)			450.00

Kan Fook Sing Motor Workshop/SKS778J/09/09/2022 15:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >