

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 13 Jun 2022)

Parts: 143

MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET Distorted	0.00	0.00	*1,585.00 F ✓
2	1		*FRONT BONNET CHROME could	0.00	0.00	*76.00 F ✓
3	1		*FRONT BONNET LOCK Dend.	0.00	0.00	*65.00 F ✓
4	1		*FRONT BONNET LOCK LOWER RH } given	0.00	0.00	*45.00 F ✓
5	1		*FRONT BONNET LOCK LOWER LH	0.00	0.00	*45.00 F ✓
6	1		*FRONT BONNET EMBLEM xcu	0.00	0.00	*40.00 F ✓
7	1		*FRONT BONNET STOPPER RH } given	0.00	0.00	*18.00 F ✓
8	1		*FRONT BONNET STOPPER LH	0.00	0.00	*18.00 F ✓
9	1		*FRONT TOP PANEL Best	0.00	0.00	*110.00 F ✓
10	1		*FRONT TOP PANEL GARNISH could	0.00	0.00	*75.00 F ✓
11	1		*FRONT BRACE PANEL Damp.	0.00	0.00	*25.00 F ✓
12	1		*FRONT HEADLAMP PANEL RH } given	0.00	0.00	*155.00 F ✓
13	1		*FRONT HEADLAMP PANEL LH } given LH Best	0.00	0.00	*155.00 F ✓
14	1		*FRONT HEADLAMP RH cracked.	0.00	0.00	*1,720.00 F ✓
15	1		*FRONT HEADLAMP LH smashed.	0.00	0.00	*1,720.00 F ✓
16	1		*FRONT GRILLE smashed	0.00	0.00	*470.00 F ✓
17	1		*FRONT GRILLE GARNISH Dend.	0.00	0.00	*110.00 F ✓
18	1		*FRONT GRILLE EMBLEM } smashed	0.00	0.00	*95.00 F ✓
19	1		*FRONT GRILLE EMBLEM BASE	0.00	0.00	*45.00 F ✓
20	1		*FRONT FENDER LH Best	0.00	0.00	*525.00 F ✓
21	1		*FRONT FENDER SHIELD LH } given	0.00	0.00	*95.00 F ✓
22	10		*FRONT FENDER SHIELD CLIP } given	0.00	0.00	*30.00 F ✓
23	1		*FRONT BUMPER Distorted	0.00	0.00	*990.00 F ✓
24	1		*FRONT BUMPER FOAM could	0.00	0.00	*95.00 F ✓
25	1		*FRONT BUMPER REINFORCEMENT Best	0.00	0.00	*175.00 F ✓
26	1		*FRONT BUMPER REINFORCEMENT BRACKET RH ?	0.00	0.00	*160.00 F ?
27	1		*FRONT BUMPER REINFORCEMENT BRACKET LH ?	0.00	0.00	*160.00 F ?
28	1		*FRONT BUMPER LOWER GRILLE could	0.00	0.00	*65.00 F ✓
29	1		*FRONT BUMPER SENSOR Dend	0.00	0.00	*153.00 F ✓
30	4		*FRONT BUMPER SENSOR COVER ?	0.00	0.00	*200.00 F ?
31	1		*FRONT BUMPER FOGLAMP COVER LH reassembled	0.00	0.00	*50.00 F ✓
32	1		*FRONT BUMPER CARRIER CENTRE ?	0.00	0.00	*150.00 F ?
33	1		*FRONT BUMPER CARRIER LH ?	0.00	0.00	*15.00 F ?
34	1		*FRONT BUMPER WIPER COVER LH Missing	0.00	0.00	*40.00 F ✓
35	1		*FRONT BUMPER WIPER HOSE reassembled	0.00	0.00	*85.00 F ✓
36	1		*AIR BUFLER TOP Beltd	0.00	0.00	*110.00 F ✓
37	1		*AIR BUFLER LOWER ?	0.00	0.00	*95.00 F ?
38	1		*AIR CON CONDENSER Dented	0.00	0.00	*720.00 F ✓
39	1		*RADIATOR could	0.00	0.00	*445.00 F ✓
40	1		*POWER STEERING PIPE	0.00	0.00	*175.00 F ?
41	1		*INTERCOOLER GARNISH ?	0.00	0.00	*265.00 F ?
42	1		*FRONT NUMBER PLATE GARNISH could	0.00	0.00	*85.00 F ✓

F=Franchise part.

Sub Total (\$\$)

11,455.00

+ Margin on L,N Items 10.00% (\$\$)

1,145.50

Kan Fook Sing Motor Workshop/SKS778J/13/06/2022 17:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS