

TPAXA
Xiao Chen

SLX 3966A 2018 March
Honda Vezel Hybrid 1496 cc
RU31267650

Front RH Fender Dented	548.60 ✓
Front RH Fender Wheel Arc Garnish ^{cut}	183.80 ✓
Front RH Fender Wheel Arc Garnish ^{new} Clips.	20(SN) ✓
Front RH Fender Inner Shield Torn	148.90 ✓
Front RH Fender Inner Shield clips. ^{new}	30(SN) ✓
Front RH Fender Emblem. ^{new}	35.70 ✓
Front RH wheel Rim. ^{cut}	280(SN) 180(SN)
Front RH Tyre ^{Not new}	280(SN) X.
Front RH Lower Arm. ^{Bent}	395.60 ✓
Front RH Shock Absorber ^{new}	373.40 X.
Front RH Knuckle Arm. ^{new}	398.40 X.
Front RH wheel Hub ^{new} Bearing. Damaged	197.80 ✓
Front RH Door Distorted	989.40 ✓
Front RH Door Lock Damaged	319.40 ✓
Front RH Door Weatherstripe. ^{new}	185.40 X.

SLX 3966A.

Front RH Door Inner Trim Board	Cracked	568.40 ✓
Front RH Door Inner Trim Board clips.	Neu	30(SN) ✓
Front RH Door Glass Regulator Gear Danged		392.80 ✓
Front RH Door Glass Regulator Motor		367.60 X
Front RH Door Outer Handle.	NE Neu	50(SN) ✓
Front RH Door Black Tape.	NE	695.90 X
Centre Pillar RH.	Repis	788.10 X
Rocker Panel RH.	Repis	598.20 ✓
Rocker Panel Outer Skirting RH.	Distorted	30(SN) ✓
Rocker Panel Outer skirting clips.	Neu	954.90 ✓
Rear RH Door	Dented	320.50 X
Rear RH Door Lock	NE Neu	181.40 X
Rear RH Door Weatherstripe.	NE Neu	68.90 ✓
Rear RH Door Vertical Weatherstripe.	Gr	598.40 ✓
Rear RH Door Inner Trim Board	Cracked	30(SN) ✓
Rear RH Door Inner Trim Board clips.	Neu	385.90 ✓
Rear RH Door Glass Regulator Gear Danged		
Rear RH Door Glass Regulator Motor.		

SLX 3966A.

Rees RH Door Black Tape	New	50(SN)	✓
		981.40	+
Rees RH Fender Repairs			
Rees RH Fender Wheel Arc Garnish	Ut	188.20	✓
	20(SN)		✓
Rees RH Fender Wheel Arc Garnish clips			
Rees RH Taillamp lower Apron	Debond	195.40	✓
		880(SN) 480(SN)	
Rees RH Wheel Rim	Ut		
		280(SN)	X
Rees RH Tyre	Not New		
		385.40	+
Rees RH Shock Absorber	Not New		
		335.40	✓
Rees RH Wheel Hub clw Bearing	Damaged		
		1845.30	+
Rees Axle	Not New		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

* acknowledged by Repairer

710570

568456

S.N: 1190

SLX 3966A.

Panel Beating

Spray Painting.

Wiring.

To spray buff coat.

To transfer front and rear door fittings.

To remove upholstery.
front.

To remove and undercarriage.

To remove rear undercarriage.

To perform wheel alignment

~~1800~~ 1000

~~1600~~ 1200

~~100~~ 30

~~150~~ 100

~~300~~ 160

~~150~~ 60

~~300~~ 220

~~350~~ 80

~~150~~ 80

2930

total: 9804.56

t/s: 7.8K.

09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: