

REF: GQ
PRS

LPC

ASSIGNMENT

COE Expired: 26/9/2027

From: Date:

Estimated Cost:

OC / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s AUTO MEGA MALL

of

Insured:

Policy No

Claims No

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$38K?

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum. 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBC2606A

Yr Regn: 21/9/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN / NV200 1.5L

c.c

-1461

Colour: White

A/C: Insured / Std / NI / NA

Sp Reading: 229046

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VSKYBAM20U0021681

Gen. Cond: Good / Fair / Poor / Burnt

Steering: norden / Jammed / Leaked / Burnt or

Brake: norden / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ROTALLA

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.L. 12-05-2022

Survey held at

W/S

12PM

Des. of Damages: Frt / Real / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

No GIA provided

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Date/Time: File

Date/Time: File

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : (Add Fee)

Survey Fee:

Transportation.

\$ + RS. \$

Photos

Other

Cost

229,046 Km.

D.O.A. = 9/5/2022
Bal. = 4 yrs 4.6 mths.
M.V. = \$38,000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Limited Partnership
Owner ID: 017C

Vehicle Details

Vehicle No.: GBC2606A
Vehicle to be Exported: No
Intended Deregistration Date: 07 Dec 2022
Vehicle Make: NISSAN
Vehicle Model: NV200 1.5L MT ABS AIRBAG 2WD 6DR
Primary Colour: White
Manufacturing Year: 2011
Engine No.: K9KF276D122869
Chassis No.: VSKYBAM20U0021681
Maximum Power Output: -
Open Market Value: \$21,872.00
Original Registration Date: 27 Sep 2011
First Registration Date: 27 Sep 2011
Transfer Count: 2
Actual ARF Paid: \$1,094.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2026
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5

PQP Paid: \$19,586.00

COE Rebate Amount: \$14,896.00

Total Rebate Amount: \$14,896.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 05 Dec 2022

OK

10,290

8,260

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: GBC2606A
Chassis No:
Engine No:

Report No :
Date : 09.05.2022

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Bumper	Damaged CUT	\$ 910.00	549 \$ 819.00
2	1	Rear Bumper Bracket LH	Necessary X SVC	\$ 85.00	\$ 76.50
3	1	Rear Bumper Bracket RH	Necessary X SVC	\$ 85.00	\$ 76.50
4	1	Rear Tail Gate Door LH	Damaged BUC	\$ 1,711.00	1,548 \$ 1,539.90
5	1	Rear Tail Gate Door RH	Damaged BUC	\$ 1,711.00	1,548 \$ 1,539.90
6	1	Rear Bumper Reflector LH	Damaged X NN	\$ 110.00	\$ 99.00
7	1	Rear Bumper Reflector RH	Damaged X NN	\$ 110.00	\$ 99.00
8	1	Rear Car Plate	Damaged X NN	\$ 40.00	\$ 36.00
9	1	Rear Car Plate Holder	Damaged X NN	\$ 40.00	\$ 36.00
10	1	Rear LH Tail Gate Garnish	Damaged CUT	\$ 355.00	\$ 319.50
11	1	Top 3rd Brake Light	Damaged X NN	\$ 387.00	\$ 348.30
12	1	Rear Left Tail Lamp	Broken X NN	\$ 556.00	\$ 500.40
13	1	Rear Right Tail Lamp	Damaged X NN	\$ 556.00	\$ 500.40
14	2	Rear LH Tail Gate Hinge	Impacted X SVC	\$ 98.00	\$ 88.20
15	2	Rear RH Tail Gate Hinge	Impacted X SVC	\$ 98.00	\$ 88.20
16	1	Rear Tail Gate Lock	Distorted X SVC	\$ 326.00	188 \$ 293.40
17	1	Rear End Panel Lock Hinge	Distorted X SVC	\$ 112.00	\$ 100.80
18	1	Rear Tail Gate weather Strips	Necessary X PD	\$ 265.00	145 \$ 238.50
19	1	Rear Tail Gate Lock	Damaged X SVC	\$ 335.00	188 \$ 301.50
20	1	Rear Tail Gate Lock Actuator	Damaged X NS	\$ 446.00	\$ 401.40
21	1	Rear End Panel	Impacted X R	\$ 795.00	\$ 715.50
				\$ 9,131.00	\$ 7,304.80

Total (Parts): \$ 9,131.00 -10% \$ 7,304.80

Labour Charges

26	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ 1,000.00	600
27	To apply anti rust coat and affected areas	\$ 120.00	60
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00	X
30	Spray painting for Rear Portions affected parts	\$ 1,000.00	700
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ -	
33	3D Wheel Alignment	\$ -	
34	To Apply Waterproofing sealer on End Panels	\$ 180.00	X
Total Labour:		\$ 3,280.00	X

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 10,584.80

Less 20% \$ 8,467.84

4 days