

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

(SUPPLEMENTARY)INSURER: **ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	10/06/2022
Vehicle Reg. No.:	SMM6609H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A)	Vehicle Reg. Date:	09/07/2019
Vehicle Colour:	METALLIC PEARL WHITE		
Engine No:	K9KF649D059887	Chassis No:	VF1RFA00962704561
Odometer:	246165 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	5,267.90
Miscellaneous Items	0.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	6,017.90
+ GST 7.00% (\$)	421.25
Nett Amount (\$)	6,439.15
+ Previous Estimates (\$)	41,664.89
Claim Total (\$)	48,104.04

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jun 2022)

Parts: M1-MPV RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SMM6609H/17/06/2022 15:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	620436650R	*FRONT FENDER INNER PANEL OUTER repair	0.00	0.00	*112.00 F	x
2	1	625124628R	*FRONT FENDER SIDE BRACKET RH bent	0.00	0.00	*226.40 F	
3	1	924549656R	*FRONT AIRCON LOWER PRESSURE PIPE COMP TO EVAP 1 puncture	0.00	0.00	*230.00 F	
4	1	924904498R	*FRONT AIRCON LOWER PRESSURE PIPE COND TO COMP dented	0.00	0.00	*203.40 F	
5	1	237065517R	*FRONT ECU UNIT COVER dented	0.00	0.00	*61.60 F	
6	1	165551527R	*FRONT ENGINE BATTERY TOP AIR INTAKE PIPE svc	0.00	0.00	*317.60 F	x
7	1	144606515R	*FRONT INTERCOOLER AIR HOSE TOP cut	0.00	0.00	*656.00 F	
8	1	231004EA0A	*FRONT ALTERNATOR cracked	0.00	0.00	*841.50 F	
9	1		*FRONT FAN BELT torn	0.00	0.00	*45.00 F	
10	1	260602165R	*FRONT HEADLAMP LH mtg cracked	0.00	0.00	*892.50 F	
11	1	113320979R	*FRONT ENGINE MOUNTING BRACKET cracked	0.00	0.00	*115.80 F	
12	1	112106137R	*FRONT ENGINE MOUNTING UPPER cracked	0.00	0.00	*152.50 F	
13	1	112383734R	*FRONT ENGINE MOUNTING CENTRE ?	0.00	0.00	*115.80 F	
14	1	112204BB0A	*FRONT ENGINE MOUNTING LOWER ?	0.00	0.00	*77.20 F	
15	1	751105359R	*FRONT CHASSIS SUPPORT RH repair	0.00	0.00	*741.70 F	

F=Franchise part.

Sub Total (\$\$)	4,789.00
+ Margin on L,N Items 10.00% (\$\$)	478.90
Total Parts (\$\$)	5,267.90

Munich Autocare Pte Ltd/SMM6609H/17/06/2022 15:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK AND REPAIR FRONT RH SUPPORT CHASSIS PANEL & ADJUST ALL AFFECTED AREA	New	250.00 x
2	TO REMOVE AND INSTALL ENGINE MOUNTING AND ALTERNATOR INCLUDING CHECK FOR PROPER FUNCTION	New	250.00 100
3	TO RESPRAY FRONT RH SUPPORT CHASSIS PANEL & ADJUST ALL AFFECTED AREA	New	250.00 x
Gross Labour Cost (\$\$)			750.00

Munich Autocare Pte Ltd/SMM6609H/17/06/2022 15:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >