

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005638/TQY3Q2**Date:** 05/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00153122100

Claimant Vehicle No : SMW747D **Insured Vehicle No :** GBL3049D

Date of Loss: 13/06/2022 Nature of Claim: TP Claim No: SNM22D204113/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW747D**

Make & Model: PORSCHE MACAN, 2.0 PDK CYP E5 (A) Engine No: 011219

Reg. Date: 19/04/2016 (Man. Year: 2016) Chassis No: WP1ZZZ95ZHLB00171

Colour: Black Odometer: 75036 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 265/45 R20 Rear Tyre Size: 295/40 R20

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,403.30	9,676.24	10,727.06	52.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,300.00	2,190.00	62.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,893.30	10,976.24	12,917.06	54.06
Approved Total (Overridden) (S\$)		8,750.00		
(S\$)	23,893.30	8,750.00	15,143.30	63.38
+ GST 7.00/7.00% (S\$)	1,672.53	612.50	1,060.03	63.38
Nett Amount (S\$)	25,565.83	9,362.50	16,203.33	63.38

INSPECTION

Date of Assignment: 15/06/2022

Date Inspected: 15/06/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2022)**Parts:** M1-SUV PORSCHE MACAN 2.0 PDK CYP E5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMW747D)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	3,256.00 FL	*2,455.00 FL
2	1		*BONNET EMBLEM	Necessary	336.00 FL	*296.70 FL
3	1		*BONNET INNER HEAT INSULATOR	Not Necessary	438.00 FL	*- FL
4	1		*SET BONNET INNER HEAT INSULATOR CLIPS	Not Necessary	80.00 FL	*- FL
5	1		*BONNET RH HINGE	Not Necessary	211.00 FL	*- FL
6	1		*BONNET LH HINGE	Not Necessary	211.00 FL	*- FL
7	1		*BONNET LOCK	Not Necessary	378.00 FL	*- FL
8	1		*FRONT BUMPER	Torn	1,621.00 FL	*1,084.90 FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
10	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	32.00 FL	*- FL
11	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	32.00 FL	*- FL
12	1		*FRONT BUMPER GRILLE	Deformed	489.00 FL	*489.00 FL
13	1		*FRONT BUMPER INNER AIR DUCT	Not Necessary	203.00 FL	*- FL
14	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	339.00 FL	*- FL
15	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	549.00 FL	*- FL
16	1		*FRONT BUMPER INNER SPONGE	Not Necessary	89.00 FL	*- FL
17	1		*FRONT BUMPER TOWING COVER	Not Necessary	72.00 FL	*- FL
18	1		*FRONT BUMPER RH SENSOR	Not Necessary	267.00 FL	*- FL
19	1		*FRONT BUMPER LH SENSOR	Not Necessary	267.00 FL	*- FL
20	1		*SUPPORT PANEL	Repair	734.00 FL	*- FL
21	1		*SUPPORT PANEL TOP GARNISH COVER	Deformed	252.00 FL	*252.00 FL
22	1		*SET SUPPORT PANEL TOP GARNISH COVER CLIPS	Necessary	50.00 FL	*20.00 FL
23	1		*RH HEADLAMP ASSY	Cracked	3,173.00 FL	*2,673.00 FL
24	1		*LH HEADLAMP ASSY	Cracked	3,173.00 FL	*2,673.00 FL
25	1		*AIRCON CONDENSER	Not Necessary	1,893.00 FL	*- FL
26	1		*RADIATOR ASSY	Not Necessary	2,512.00 FL	*- FL
27	1		*BONNET BODY WRAP STICKER	Cut	850.00 FS	*400.00 FS
28	1		*FRONT BUMPER BODY WRAP STICKER	Necessary	700.00 FS	*300.00 FS
29	1		*FRONT NUMBER PLATE	Not Necessary	70.00 FS	*- FS
30	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,477.00	10,673.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,073.70	997.36
Total Parts (\$\$)	20,403.30	9,676.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	70.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR .TO REFILL AIRCON GAS	New	250.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY ,HOSES AND PIPES TO ASSIST REPAIR .TO REFILL COOLANT	New	250.00	0.00
7	REFOCUS AND ADJUST HEADLAMPS ASSY	New	100.00	40.00
Gross Labour Cost (\$)			3,490.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >