

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005640/TQY3E2**Date:** 06/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00167752100
Claimant Vehicle No :	SML4432T	Insured Vehicle No :	SJH7884J
Date of Loss:	15/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203362/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML4432T	Engine No:	LEB5615006
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71078968
Reg. Date:	22/05/2019 (Man. Year: 2018)	Odometer:	170110 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	16,272.48	4,571.04	11,701.44	71.91	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,420.00	660.00	3,760.00	85.07	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	20,692.48	5,231.04	15,461.44	74.72	
Approved Total (Overridden) (S\$)		4,150.00			
	(S\$)	20,692.48	4,150.00	16,542.48	79.94
	+ GST 8.00/8.00% (S\$)	1,655.40	332.00	1,323.40	79.94
	Nett Amount (S\$)	22,347.88	4,482.00	17,865.88	79.94

INSPECTION

Date of Assignment:	14/06/2022		
Date Inspected:	15/06/2022	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2023)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SML4432T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,160.70 FL	*986.00 FL
2	1		*FRONT BUMPER TOWING COVER	Deformed	20.70 FL	*20.70 FL
3	1		*FRONT BUMPER LOWER LIP	Cracked	196.50 FL	*196.50 FL
4	1		*FRONT BUMPER LOWER GRILLE	Deformed	346.70 FL	*233.00 FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Deformed	29.50 FL	*29.50 FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	29.50 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	347.60 FL	*347.60 FL
8	1		*FRONT BUMPER ENGINE UNDER COVER CENTRE	Not Necessary	360.90 FL	*- FL
9	1		*FRONT FENDER RH	Not Necessary	490.20 FL	*- FL
10	1		*FRONT FENDER LH	Not Necessary	490.20 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	170.00 FL	*- FL
12	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	170.00 FL	*- FL
13	1		*FRONT GRILLE TOP	Cracked	548.00 FL	*548.00 FL
14	1		*FRONT GRILLE LOWER	Not Necessary	159.00 FL	*- FL
15	1		*FRONT GRILLE EMBLEM	Necessary	89.00 FL	*89.00 FL
16	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	245.00 FL	*- FL
17	1		*FRONT HEADLAMP ASSEMBLY RH (LED)	Cracked	1,980.10 FL	*1,544.00 FL
18	1		*FRONT HEADLAMP ASSEMBLY LH (LED)	Cracked	1,980.10 FL	*1,544.00 FL
19	1		*FRONT HEADLAMP LOWER BRACKET RH	Cracked	56.50 FL	*56.50 FL
20	1		*FRONT HEADLAMP LOWER BRACKET LH	Cracked	56.50 FL	*56.50 FL
21	1		*FRONT BONNET	Not Necessary	970.20 FL	*- FL
22	1		*FRONT BONNET HINGE RH	Not Necessary	45.60 FL	*- FL
23	1		*FRONT BONNET HINGE LH	Not Necessary	45.60 FL	*- FL
24	1		*FRONT BONNET LOCK	Not Necessary	163.70 FL	*- FL
25	1		*FRONT BONNET LOCK CABLE	Not Necessary	75.60 FL	*- FL
26	2		*FRONT BONNET INNER RUBBER (FRONT)	Not Necessary	144.40 FL	*- FL
27	2		*FRONT BONNET INNER RUBBER (SIDE)	Not Necessary	137.40 FL	*- FL
28	1		*FRONT BONNET INSULATOR	Not Necessary	149.20 FL	*- FL
29	1		*FRONT SUPPORT PANEL	Not Necessary	896.00 FL	*- FL
30	1		*FRONT WIRE HARNESS	Not Necessary	1,169.90 FL	*- FL
31	1		*AIR GUARD	Not Necessary	70.90 FL	*- FL
32	1		*RADIATOR	Not Necessary	1,502.20 FL	*- FL
33	1		*RADIATOR SIDE GARNISH RH	Not Necessary	75.80 FL	*- FL
34	1		*RADIATOR SIDE GARNISH LH	Not Necessary	75.80 FL	*- FL
35	1		*RADIATOR FAN MOTOR	Not Necessary	398.80 FL	*- FL
36	1		*RADIATOR FAN COWLING	Not Necessary	165.10 FL	*- FL
37	1		*RADIATOR FAN BLADE	Not Necessary	89.20 FL	*- FL
38	1		*RADIATOR SPARE TANK	Not Necessary	74.70 FL	*- FL
39	1		*AIRCON CONDENSER	Not Necessary	988.70 FL	*- FL
40	1		*AIRCON FAN BLADE	Not Necessary	84.80 FL	*- FL
41	1		*AIRCON FAN MOTOR	Not Necessary	384.90 FL	*- FL
42	1		*AIRCON FAN COWLING	Not Necessary	149.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*AIR CLEANER RESONATOR	Not Necessary	150.90 FL	*- FL
44	1		*AIR CLEANER RESONATOR DUCT	Not Necessary	95.10 FL	*- FL
45	1		*AIR DUCT	Not Necessary	64.50 FL	*- FL
46	1		*AIR FLEXIBLE DUCT	Not Necessary	142.50 FL	*- FL
47	1		*FRONT TEMPERATURE SENSOR	Not Necessary	158.60 FL	*- FL
48	1		*BUZZER	Not Necessary	164.50 FL	*- FL
49	1		*BATTERY TRAY	Not Necessary	42.20 FL	*- FL
50	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
51	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
52	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
53	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
54	1		*RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
55	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS
56	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
57	2		*FRONT FENDER SEALANT	Not Necessary	300.00 FS	*- FS
58	1		*FRONT BUMPER LOWER SPOILER - AFTERMARKET	Not Necessary	600.00 FS	*- FS
59	1		*SET FRONT BUMPER SENSOR	Not Necessary	350.00 FS	*- FS
60	1		*SET FRONT BUMPER CANARDS - AFTERMARKET	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,793.10	5,701.30
- List Item Discount on L Items 20.00/20.00% (\$)	3,520.62	1,130.26
Total Parts (\$)	16,272.48	4,571.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	1,600.00	300.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	300.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX AIRCON CONDENSER & TOP UP GAS	New	150.00	0.00
5	TO REMOVE & REFIX RADIATOR & CONDUCT PRESSURE TEST	New	150.00	0.00
6	TO REMOVE & REFIX FRONT BUMPER SENSOR	New	120.00	30.00
7	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	0.00
8	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
9	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
			Gross Labour Cost (\$)	4,420.00
				660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >