

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22005645/EVCE2

**Date:** 30/08/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001995973		
<b>Claimant Vehicle No :</b>	SLQ1200B	<b>Insured Vehicle No :</b>	SLC5230L		
Date of Loss:	10/06/2022	Nature of Claim:	TP	Claim No:	276542

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1200B	Engine No:	161114133715204PT
Make & Model:	JAGUAR XJ, 2.0 TSS SWB SR (A)	Chassis No:	SAJAC12M9FPV81789
Reg. Date:	20/05/2015 (Man. Year: 2014)	Odometer:	116780 km
Colour:	Black		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,234.23	9,345.65	5,888.58	38.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,040.00	2,360.00	69.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,634.23</b>	<b>10,385.65</b>	<b>8,248.58</b>	<b>44.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,634.23</b>	<b>8,300.00</b>	<b>10,334.23</b>	<b>55.46</b>

### INSPECTION

Date of Assignment:	14/06/2022	
Date Inspected:	15/06/2022	Inspected At: Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre Singapore 627603
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
<b>Parts:</b>	143	JAGUAR XJ 2.0 TSS SWB SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ1200B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented	2,563.10 FL	*2,563.10 FL
2	1	*REAR BUMPER CHROME TRIM	Broken	531.70 FL	*365.00 FL
3	2	*REAR BUMPER BRACKET MOUNTING OUTER LH & RH	Broken	151.20 FL	*151.20 FL
4	2	*REAR BUMPER BRACKET MOUNTING INNER LH & RH	Not Necessary	142.80 FL	*- FL
5	1	*REAR BUMPER LOWER COVER	Crushed	460.00 FL	*460.00 FL
6	2	*REAR BUMPER SPONGE LH & RH	Not Necessary	460.00 FL	*- FL
7	1	*REAR BUMPER REINFORCEMENT	Not Necessary	1,590.00 FL	*- FL
8	1	*REAR BUMPER REVERSE SENSOR (4PCS)	Shorted (2pcs only)	1,588.00 FL	*364.00 FL
9	4	*REAR BUMPER SENSOR HOLDER	Necessary	182.00 FL	*120.00 FL
10	2	*REAR TAILLAMP LH & RH	Broken	2,476.00 FL	*2,476.00 FL
11	1	*BOOTLID	Dented	3,179.50 FL	*3,179.50 FL
12	1	*BOOTLID LOGO EMBLEM	Necessary	81.10 FL	*81.10 FL
13	1	*BOOTLID JAGUAR EMBLEM	Necessary	88.80 FL	*88.80 FL
14	1	*BOOTLID XJ EMBLEM	Necessary	68.80 FL	*68.80 FL
15	1	*BOOTLID LOCK	Bent	549.00 FL	*270.00 FL
16	1	*BOOTLID WEATHERSTRIP	Torn	256.00 FL	*256.00 FL
17	1	*REAR END PANEL	Not Necessary	1,959.00 FL	*- FL
18	1	*REAR END PANEL TOP GARNISH	Broken	146.21 FL	*146.21 FL
19	1	*REVERSE CAMERA	Not Necessary	891.30 FL	*- FL
20	2	*REAR NUMBER PLATE LAMP LH & RH	Cut	264.00 FL	*264.00 FL
21	1	*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
22	1	*SET REAR BUMPER RIVET & CLIPS	Necessary	100.00 FS	*40.00 FS
23	1	*SET REAR BOOTLID INNER TRIMBOARD CLIPS	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>17,878.51</b>	<b>10,973.71</b>
<b>- List Item Discount on L Items 15.00/15.00% (\$)</b>	2,644.28	1,628.06
<b>Total Parts (\$)</b>	<b>15,234.23</b>	<b>9,345.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE & PANEL BEATING AFFECTED PARTS FOR REAR PORTION	New	1,200.00	400.00
2	TO SPRAY PAINT ON AFFECTED AREAS FOR REAR PORTION	New	1,000.00	400.00
3	TO REMOVE / REPLACE / REINSTALL REAR BOOTLID COMPONENTS	New	150.00	50.00
4	TO REMOVE / REPLACE / REINSTALL REAR PANEL UPHOLSTERY & TRIM	New	200.00	0.00
5	TO APPLY ANTI-RUST ON AFFECTED AREAS	New	100.00	30.00
6	TO REMOVE / REPLACE / REINSTALL REVERSE SENSORS	New	150.00	30.00
7	TO REMOVE / REPLACE / REINSTALL REVERSE CAMERA	New	100.00	80.00
8	TO CHECK WIRING FOR REAR PORTION	New	100.00	50.00
9	TO PERFORM SYSTEM DIAGNOSTIC & RESET ECU	New	400.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,400.00</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >