

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22005650/TPA3Q2
Date: 20/10/2022

REFERENCE

| | | |
|--|-------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 1900233173 | |
| Claimant Vehicle No : SHB423H | Insured Vehicle No : GBH9795P | |
| Date of Loss: 09/06/2022 | Nature of Claim: TP | Claim No: 9337221593SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | |
|--|-------------------------------|--|
| Reg No: SHB423H | | |
| Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) | Engine No: 2ZR6125766 | |
| Reg. Date: 08/09/2014 (Man. Year: 2014) | Chassis No: JTDKN36U605748535 | |
| Colour: Maroon | Odometer: 732031 km | |
| Engine Capacity: 1798 cc | | |
| Market Value/New Car Price: N/A | | |
| Sum Insured (S\$): Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | |
|------------------------------|-----------------------------|------------------------------|
| General Condition: | Steering (Serviceable): Yes | Footbrake (Serviceable): Yes |
| Handbrake (Serviceable): Yes | Engine Modification: No | Pre-accident Condition: |

CONDITION OF TYRES

| | | |
|-------------------------------|------------------------------|--|
| Front Tyre Size: 195/65 R15 | Rear Tyre Size: 195/65 R15 | |
| Front Left Side: Sailun 6 mm | Rear Left Side: Sailun 6 mm | |
| Front Right Side: Sailun 6 mm | Rear Right Side: Sailun 6 mm | |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 2,322.50 | 359.70 | 1,962.80 | 84.51 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,794.00 | 430.00 | 1,364.00 | 76.03 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,116.50 | 789.70 | 3,326.80 | 80.82 |
| Approved Total (Overridden) (S\$) | | 700.00 | | |
| Nett Amount (S\$) | 4,116.50 | 700.00 | 3,416.50 | 83.00 |
| + Car Rental (3.0 x S\$102.72/day) (S\$) | | 308.16 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 1,010.16 | | |
| Global Sum Settlement (S\$) | | 1,010.00 | | |

INSPECTION

| | | |
|--------------------------------------|---------------|--|
| Date of Assignment: 10/06/2022 | | |
| Date Inspected: 10/06/2022 | Inspected At: | Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705 |
| Estimated Period of Repair: 2.0 days | | |

10/20/22, 10:46 AM

Adjuster Report

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------------|-----------------|
| 1 | 1 | | *BUMPER REAR (DISC 25%) | Deformed | 458.60 F | *343.95 F |
| 2 | 1 | | *BUMPER CLIPS (DISC 25%) (10 PCS) | Necessary | 21.00 F | *15.75 F |
| 3 | 1 | | *BUMPER REINFORCEMENT REAR | Not Necessary | 205.70 F | *- F |
| 4 | 1 | | *ARM SUB-ASSY ,RR BUMPER RH | Not Necessary | 139.60 F | *- F |
| 5 | 1 | | *ARM SUB-ASSY ,RR BUMPER LH | Not Necessary | 139.60 F | *- F |
| 6 | 1 | | *ANTENNA ELECTRICAL LOWER REAR | Not Necessary | 157.40 F | *- F |
| 7 | 1 | | *SENSOR REVERSE | Not Necessary | 180.00 F | *- F |
| 8 | 1 | | *BUMPER SIDE RETAINER RR/LH | Not Necessary | 94.80 F | *- F |
| 9 | 1 | | *BUMPER SIDE RETAINER RR/RH | Not Necessary | 94.80 F | *- F |
| 10 | 1 | | *BUMPER LIP REAR | Not Necessary | 228.90 F | *- F |
| 11 | 1 | | *END PANEL | Not Necessary | 602.10 F | *- F |
| | | | | | F=Franchise part. | |
| | | | | | Total Parts (S\$) | 2,322.50 359.70 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | PANEL BEATING & BODY WORK | New | 676.00 | 200.00 |
| 2 | SPRAY PAINT | New | 738.00 | 200.00 |
| 3 | TO WASH AND VACUUM | New | 60.00 | 0.00 |
| 4 | TO APPLY RUST-PROOFING ON AFFECTED AREA | New | 100.00 | 0.00 |
| 5 | TO TEST AND REFIX REVERSE SENSOR SYSTEM | New | 120.00 | 30.00 |
| 6 | TO REPLACE SUNDRY PARTS | New | 100.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,794.00 | 430.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >