



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300193

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 11/01/2023
Reference CC3/CTI22005651/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 4500L
Insured Veh. GX 8364M
Claim No. SNM22D204101/C02
Policy No. DMCVSNA00004752201
Accident Date 08/06/2022
Inspection Date 10/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22005651/Tpa3q2 Date: 11/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 8364M	Veh. Inspected	SHC 4500L	
Policy No.	DMCVSNA00004752201	Coverage (\$)	0.00	
Claim No.	SNM22D204101/C02	Excess (\$)	0.00	
Assign From		Assign Date	10/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U405748176	Colour	MAROON	
Odometer	665628 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	6 mm	
L/H Front Tyre	195/65 R15	SAILUN	6 mm	
R/H Rear Tyre	195/65 R15	SAILUN	6 mm	
L/H Rear Tyre	195/65 R15	SAILUN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2022	Inspection Date	10/06/2022	
Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4500L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BRACKET ,FR BUMPER (DISC 25%)	DEFORMED	110.40	82.80
1	BUMPER GRILLE SUB-ASSY ,LOWER (DISC 25%)	CRACKED	311.10	233.33
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	TORN	78.80	59.10
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	NUMBER PLATE FRAME (SN)	BENT	12.00	12.00
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY ,FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY ,FR BUMPER RH	NOT NECESSARY	250.40	-
1	DEFLECTOR ,RADIATOR RH	NOT NECESSARY	83.50	-
1	DEFLECTOR ,RADIATOR LH	NOT NECESSARY	77.00	-
1	COVER ,FR BUMPER HOLE LH	NOT NECESSARY	18.50	-
1	COVER ,FR BUMPER HOLE RH	NOT NECESSARY	18.50	-
1	BUMPER GRILLE SUB-ASSY ,LOWER	NOT NECESSARY	311.10	-
1	FOG LAMP RH	NOT NECESSARY	295.20	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-
1	LENS & BODY FR TURN LH	NOT NECESSARY	511.80	-
1	LENS & BODY FR TURN RH	NOT NECESSARY	511.80	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	GRILLE, RADIATOR LOWER NO.2	NOT NECESSARY	94.60	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	HEAD LAMP LH	NOT NECESSARY	945.20	-

Report Ref No. CC3/CTI22005651/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEAD LAMP RH	NOT NECESSARY	945.20	-
			8,473.50	840.69
	LABOUR			
	PANEL BEATING & BODY WORK .		676.00	200.00
	SPRAY PAINT.		738.00	200.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION .	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA .	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			1,794.00	400.00
GRAND TOTAL			10,267.50	1,240.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CC3/CTI22005651/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 4500L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 4500L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 4500L

RE-INSPECTION

