

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005659/KPA3Q2**Date:** 23/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900147978
Claimant Vehicle No :	SFA10U	Insured Vehicle No :	SMN5058Z
Date of Loss:	13/06/2022	Nature of Claim:	TP
		Claim No:	0904095113SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA10U	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Chassis No:	LRW3F7FA1MC384814
Reg. Date:	27/12/2021 (Man. Year: 2021)	Odometer:	13737 km
Colour:	Metallic Pearl Dark Blue		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,685.10	2,924.64	1,760.46	37.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	940.00	840.00	47.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,465.10	3,864.64	2,600.46	40.22
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	15/06/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	15/06/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cut	1,308.41 FL	*1,308.41 FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	*Check	7.48 FL	*- FL
3	1		*FRONT BUMPER	Buckled / Cracked	495.33 FL	*495.33 FL
4	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	9.35 FL	*9.35 FL
5	1		*FRONT BUMPER UPPER BRACKET RH	Necessary	1.87 FL	*1.87 FL
6	1		*FRONT BUMPER GARNISH COVER RH	Cut	7.54 FL	*7.54 FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	271.03 FL	*- FL
8	1		*FRONT BUMPER ABSORBER FOAM	Serviceable	46.73 FL	*- FL
9	1		*FRONT BUMPER PARKING SENSOR	*Check	158.88 FL	*- FL
10	1		*FRONT BUMPER PARKING SENSOR BRACKET	*Check	4.67 FL	*- FL
11	1		*FRONT FENDER RH	Bent	448.60 FL	*448.60 FL
12	1		*FRONT FENDER INNER SHIELD RH	*Check	116.82 FL	*- FL
13	1		*FRONT RIM RH	Dented	878.50 FL	*878.50 FL
14	1		*FRONT ABSORBER RH	*Check	429.91 FL	*- FL
15	1		*FRONT UPPER ARM RH	*Check	116.82 FL	*- FL
16	1		*FRONT LOWER ARM RH	*Check	233.64 FL	*- FL
17	1		*FRONT KNUCKLE ARM RH	*Check	420.56 FL	*- FL
18	1		*FRONT WHEEL BEARING HUB RH	*Check	149.53 FL	*- FL
19	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,195.67	3,239.60
- List Item Discount on L Items 10.00/10.00% (\$)	510.57	314.96
Total Parts (\$)	4,685.10	2,924.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE & REPLACE ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	500.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER RH & ETC	New	500.00	440.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH ,FRONT UPPER & LOWER ARM RH ,FRONT KNUCKLE ARM RH ,FRONT WHEEL BEARING HUB RH & ETC (*Check)	New	300.00	0.00
5	TO WHEEL ALIGNMENT & BALANCING	New	90.00	20.00
6	TO DAIGNOSIS FAULT CODE & RESET MEMORY (*Check)	New	150.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	20.00
Gross Labour Cost (S\$)			1,780.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >