



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 1453Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,537.50	1,537.50
1	FRONT BUMPER LOWER SPOILER	DEFORMED	334.30	334.30
1	FRT BUMPER TRIM RH	NOT NECESSARY	136.60	-
1	FTR GRILLE TRIM RH	CUT	133.70	133.70
1	TURN SIGNAL INDICATOR RH	CUT	510.50	510.50
4	EXPANSION RIVET	NECESSARY	9.20	9.20
1	BUMPER REINFORCEMENT HOLDER RH	* CHECK	39.30	-
1	FRONT GRILLE TRIM CENTER	NOT NECESSARY	1,105.70	-
1	FRONT GRILLE RH	NOT NECESSARY	94.80	-
1	AIR GUIDE RH	NOT NECESSARY	125.60	-
1	TRIM FOR PARK ASSIST RH	NECESSARY	52.60	52.60
4	SENSOR CENTER	NOT NECESSARY	1,056.80	-
2	SENSOR PRIMED OUTER	* CHECK	472.40	-
6	SENSOR GASKET	NECESSARY	19.80	19.80
1	BRACKET, CHARGE AIR COOLER RH	* CHECK	249.10	-
2	CLAMP	* CHECK	3.20	-
1	RETAINER FOR ULTRASOUND SE	NECESSARY	39.80	39.80
1	RETAINER FOR ULTRASOUND SE	NECESSARY	39.80	39.80
1	RETAINER FOR ULTRASOUND SE	NECESSARY	39.80	39.80
1	RETAINER FOR ULTRASOUND SE	NECESSARY	39.80	39.80
1	BRACKET FOR PARK ASSIST	NECESSARY	41.70	41.70
1	BRACKET FOR PARK ASSIST	NECESSARY	41.70	41.70
1	HEADLIGHT BRACKET RH	* CHECK	85.80	-
1	STRUT BRACE RH	NOT NECESSARY	109.20	-
1	CROSS MEMBER PEDESTRIAN	* CHECK	253.40	-
1	BONNET	DENTED	3,983.20	3,983.20
2	GASKET FOR ENGINE COVER	NECESSARY	18.20	18.20
1	P000-043-305-51-/CAVITY PRESERVATION (AK	NECESSARY	72.40	72.40
1	PORSCHE CREST	NECESSARY	275.30	275.30
1	DESK PAD CREST	NECESSARY	17.60	17.60

Report Ref No. CS/SMO22005660/Ance2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	HOOD BADGE NUT	NECESSARY	3.80	3.80
			10,942.60	7,210.70
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	TO REMOVE / REPLACE BONNET, FRT BUMPER, & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		3,900.00	3,120.00
	TO RESPRAY BONNET, FRT BUMPER.		2,600.00	2,400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET.		150.00	150.00
	TO TRANSFERCTHE FRONT BUMPER SENSORS.		300.00	150.00
	TO APPLY SPECIAL CERAMIC COATING. (NPA)	NOT NECESSARY	-	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			8,050.00	6,570.00
GRAND TOTAL			19,042.60	13,800.70
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,103.20 NETT)				13,800.70

Report Ref No. CS/SMO22005660/Ance2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.