

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005663/ANY3E2

Date: 20/09/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00049832200
Claimant Vehicle No: SKT482G Insured Vehicle No: GX4054J
Date of Loss: 13/06/2022 Nature of Claim: TP Claim No: SNM22D204150/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT482G**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FC9H289821
Reg. Date: 16/10/2009 (Man. Year: 2009) Chassis No: KNAFW411MA5121071
Colour: Green Odometer: 208476 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,400.50	3,786.70	2,613.80	40.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,840.00	720.00	28.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,960.50	5,626.70	3,333.80	37.21
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	8,960.50	4,500.00	4,460.50	49.78
+ GST 7.00/7.00% (S\$)	627.24	315.00	312.24	49.78
Nett Amount (S\$)	9,587.74	4,815.00	4,772.74	49.78

INSPECTION

Date of Assignment: 14/06/2022

Date Inspected: 15/06/2022 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2022)
Parts: 143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT482G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	948.00 FL	*948.00 FL
2	1		*REAR BOOTLID LOGO EMBLEM	Necessary	43.00 FL	*43.00 FL
3	2		*REAR BOOTLID HINGE L/R	Not Necessary	124.00 FL	*- FL
4	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	132.00 FL	*- FL
5	1		*REAR BOOTLID MECHANISM LOCK	Damaged	105.00 FL	*105.00 FL
6	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	60.00 FL	*- FL
7	1		*REAR BOOTLID OUTER HANDLE	Not Necessary	206.00 FL	*- FL
8	1		*REAR BOOTLID WEATHERSTRIP	Cut	90.00 FL	*90.00 FL
9	1		*REAR BUMPER	Deformed	548.00 FL	*548.00 FL
10	3		*REAR BUMPER LOWER BRACKET	Necessary	84.00 FL	*84.00 FL
11	1		*REAR BUMPER LOWER LID	Deformed	101.00 FL	*101.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	302.00 FL	*302.00 FL
13	1		*REAR BUMPER REINFORCEMENT BRACKET L/R	N/S Bent	184.00 FL	*92.00 FL
14	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	736.00 FL	*368.00 FL
15	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	80.00 FL	*80.00 FL
16	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	194.00 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	42.00 FL	*42.00 FL
18	1		*REAR BUMPER SPONGE	Cracked	141.00 FL	*141.00 FL
19	1		*REAR END PANEL	Dented	262.00 FL	*262.00 FL
20	1		*REAR END PANEL INNER TOP GARNISH	Deformed	52.00 FL	*52.00 FL
21	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	60.00 FL	*- FL
22	1		*REAR EXHAUST SILENCER BOX	Not Necessary	696.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM BOARD L/R	Torn	274.00 FL	*274.00 FL
24	1		*REAR FLOOR PANEL TOP BOARD COVER	Deformed	139.00 FL	*139.00 FL
25	2		*REAR TAILLAMP L/R	Cracked	392.00 FL	*392.00 FL
26	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*REAR BOOTLID NUMBER PLATE	Not Necessary	25.00 FS	*- FS
28	1		*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BOOTLID OUTER HANDLE CLIPS	Necessary	40.00 FS	*10.00 FS
30	1		*REAR BOOTLID TOP SPOILER	Repair	600.00 FS	*- FS
31	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
33	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Necessary	100.00 FS	*60.00 FS
34	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,000.00	4,193.00
- List Item Discount on L Items 10.00/10.00% (\$)	599.50	406.30
Total Parts (\$)	6,400.50	3,786.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
3	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	0.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
6	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	60.00
7	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	800.00
			Gross Labour Cost (\$)	1,840.00
			2,560.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >