10/12/22, 9:20 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd. Our File No: CS/AIS22005665/AVY3M4 79 Robinson Road #09-01

Date: 12/10/2022 Singapore 068897

REFERENCE

Insured/Claimant: AMM LEASING PTE LTD Policy No: SPM71000000515

Date of Loss: 11/06/2022 Nature of Claim: OD Claim No: AMMAISCL2022-00053JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM1701T**

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEHU364498

Reg. Date: 23/03/2017 (Man. Year: 2017) Chassis No: KMHC851CVHU028867

Colour: White Odometer: 191094 km

Engine Capacity: 1580 cc Market Value/New Car Price: S\$72,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm Front Right Side: Rear Right Side: Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts | | 7,342.17 | 3,775.86 | 3,566.31 | 48.57 |
| Miscellaneous Items | | 450.00 | 203.50 | 246.50 | 54.78 |
| Labour | | 2,620.00 | 1,410.00 | 1,210.00 | 46.18 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 10,412.17 | 5,389.36 | 5,022.81 | 48.24 |
| | - Excess (S\$) | 0.00 | 2,000.00 | -2,000.00 | |
| | (S\$) | 10,412.17 | 3,389.36 | 7,022.81 | 67.45 |
| | + GST 7.00/7.00% (S\$) | 728.86 | 237.26 | 491.60 | 67.45 |
| | Nett Amount (S\$) | 11,141.03 | 3,626.62 | 7,514.41 | 67.45 |

INSPECTION

Date of Assignment: 14/06/2022 Present Location: Automobile Integrated Management Pte Ltd (HQ)

AUTOMOBILE INTEGRATED MANAGEMENT

PTE LTD (AIM) Date Inspected: 15/06/2022 Inspected At:

23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING)

SINGAPORE 415933

Estimated Period of Repair: 5.0 days

Adjuster: **ADRIAN LING** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2022)

Parts: 143 HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM1701T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|------------|-----------|
| 1 | 1 | | *Front bumper (WCP) | Distorted | 230.00 F | *280.00 F |
| 2 | 1 | | *Front bumper clip @ \$2.00 X 12PCS (WCP) | Not Necessary | 24.00 F | *-F |
| 3 | 1 | | *Front bumper lower lip | Not Necessary | 150.00 F | *-F |
| 4 | 1 | | *Front bumper lower grille (WCP) | Deformed | 55.00 F | *150.00 F |
| 5 | 1 | | *n/s Front fog lamp | Missing | 330.00 F | *330.00 F |
| 6 | 1 | | *n/s Front fog lamp trim | Deformed | 65.00 F | *65.00 F |
| 7 | 1 | | *Front bumper foam (WCP) | Cracked | 60.00 F | *60.00 F |
| 8 | 1 | | *Front bumper beam (WCP) | Not Necessary | 420.00 F | *-F |
| 9 | 1 | | *Front bumper lower beam | Cracked | 65.00 F | *65.00 F |
| 10 | 1 | | *Front bumper side retainer @ \$19.60 X 2 PCS | N/s Damaged | 39.20 F | *19.60 F |
| 11 | 1 | | *Front bumper top garnish (WCP) | Not Necessary | 35.00 F | *-F |
| 12 | 1 | | *Front bumper top garnish rubber seal | Not Necessary | 20.00 F | *-F |
| 13 | 1 | | *Front grille (WCP) | Cracked | 550.00 F | *550.00 F |
| 14 | 1 | | *Front grille base (WCP) | Not Necessary | 350.00 F | *-F |
| 15 | 1 | | *Radar sensor | Not Necessary | 450.00 F | *- F |
| 16 | 1 | | *Front actuator X 2PCS (WCP) | Not Necessary | 230.00 F | *-F |
| 17 | 1 | | *Parking sensor wire harness | Snapped | 145.00 F | *220.00 F |
| 18 | 1 | | *Headlamp garnish X 2PCS (WCP) | Cut | 65.00 F | *70.00 F |
| 19 | 1 | | *n/s Front fender (WCP) | Dented | 220.00 F | *230.00 F |
| 20 | 1 | | *n/s Front fender inner cowling clips @ \$2.00 X 8 PCS | Not Necessary | 16.00 F | *-F |
| 21 | 1 | | *n/s Front fender BLUE DRIVE lettering (WCP) | Necessary | 25.00 F | *25.00 F |
| 22 | 1 | | *Support guard (WCP) | Cracked | 350.00 F | *350.00 F |
| 23 | 1 | | *Support guard top garnish (WCP) | Deformed | 35.00 F | *38.00 F |
| 24 | 1 | | *n/s Air guide (WCP) | Deformed | 85.00 F | *85.00 F |
| 25 | 1 | | *Main fuse box (WCP) | Not Necessary | 950.00 F | *- F |
| 26 | 1 | | *Engine under plastic (WCP) | Cracked | 125.00 F | *120.00 F |
| 27 | 1 | | *n/s Front fender inner cowling (WCP) | Not Necessary | 80.50 F | *- F |

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------|--------------|-----------|------------------------------------|--|------------|-----------|
| 28 | 1 | | *headlamp (@\$550 x 2pcs) (WCP) | N/s Smashed | 1,100.00 F | *550.00 F |
| 29 | 1 | | *Parking sensors x 2pcs (WCP) | Repeated | 180.00 F | *- F |
| <u>Sup</u> | <u>pleme</u> | entary #1 | | | | |
| 30 | 1 | | *LOWER GRILLE MOLDING (WCP) | Damaged | 70.00 F | *70.00 F |
| <u>Sup</u> | pleme | entary #2 | | | | |
| 31 | 1 | - | *BUZZER-PIEZO (WCP) | Damaged | 70.00 F | *70.00 F |
| 32 | 1 | | *BRACKET-FRT BUMPER SIDE LH (WCP) | Damaged | 15.00 F | *15.00 F |
| 33 | 1 | | *FRONT GRILE MLDG (WCP) | Damaged | 70.00 F | *70.00 F |
| F=Fra | nchise | part. | ` , | | - | |
| | | | | Sub Total (S\$) | 6,674.70 | 3,432.60 |
| | | | | + Margin on L,N Items 10.00/10.00% (S\$) | • | 343.26 |
| | | | | Total Parts (S\$) | 7,342.17 | 3,775.86 |
| | | | Report was uns | submitted during this print-out. | | |

Recommended Miscellaneous Items

| No | Qty | Particulars | | Repairer's | Amount |
|-----|-------|--|-----------------|------------|--------|
| Mis | cella | neous Items | | | |
| 1 | 1 | Front parking sensor (1 Piece Damaged)(WCP) (10%) | | 450.00 | 203.50 |
| | | | Sub Total (S\$) | 450.00 | 203.50 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|---------------------|------------|----------|
| Lab | our Items | | | |
| 1 | Labour charges to remove and refix of parts and panel beating | g. New | 900.00 | 600.00 |
| 2 | To check electrical lighting. | New | 80.00 | 30.00 |
| 3 | Re-route wire harness | New | 120.00 | 50.00 |
| 4 | To install of front parking sensor. | New | 80.00 | 50.00 |
| 5 | Top up aircon gas | New | 80.00 | 40.00 |
| 6 | Top up radiator coolant | New | 80.00 | 40.00 |
| 7 | Scan fault code and reprogramm radar sensor | New | 480.00 | 0.00 |
| 8 | Spray painting. | New | 800.00 | 600.00 |
| | Gross | s Labour Cost (S\$) | 2,620.00 | 1,410.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >