



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 3683K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	697.80	525.30
1	FRONT BONNET	BENT	850.00	770.10
1	REAR BUMPER	BENT	730.00	561.20
1	REAR BOOTLID	BENT	930.00	930.00
1	REAR PANEL	TO REPAIR SEE LABOUR	430.00	-
1	REAR PANEL GARNISH	DISTORTED / DENTED	290.00	290.00
2	REAR LAMP @\$340.00	O/S CRACKED	680.00	340.00
1	REAR BOOTLID EMBLEM (HONDA)	NECESSARY	55.00	55.00
1	REAR BOOTLID EMBLEM (FIT)	NECESSARY	40.00	40.00
1	REAR BOOTLID LOCK	DENTED	210.00	210.00
1	REAR TAILGATE GARNISH	SERVICEABLE	550.00	-
	LESS 20% DISCOUNT		-1,092.56	-744.32
			4,370.24	2,977.28
	<u>SPECIAL NETT ITEMS</u>			
1	NO PLATE AND HOLDER (SN)	BENT	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	SPRAY FRONT AND REAR PORTION.		800.00	800.00
	LABOUR TO REPLACE FRONT AND REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR PANEL.		900.00	700.00
	TO REINSTATE WINDSCREEN.		150.00	120.00
	ANTI RUST.		50.00	50.00
			1,900.00	1,670.00
	GRAND TOTAL		6,310.24	4,687.28

Report Ref No. CS/INC22005671/Kty3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,700.00
---	--	--	-----------------

Report Ref No. CS/INC22005671/Kty3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.