

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22005673/KQY3E2

Date: 14/07/2022

REFERENCE

Insured/Claimant:	BIS MOTORING PTE LTD	Policy No:	MCF22A00000100	Claim No:	DMCF2200093H
Date of Loss:	11/06/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH6127H	Engine No:	K9KF649D059509
Make & Model:	RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A)	Chassis No:	VF1RFA00861978016
Reg. Date:	28/01/2019 (Man. Year: 2018)	Odometer:	217560 km
Colour:	Metallic Light Brown		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Tourador 8 mm	Rear Left Side:	Tourador 8 mm
Front Right Side:	Tourador 8 mm	Rear Right Side:	Tourador 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,096.02	11,190.53	8,905.49	44.31
Miscellaneous Items	94.00	94.00	0.00	0.00
Labour	3,030.00	1,270.00	1,760.00	58.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,220.02	12,554.53	10,665.49	45.93
Approved Total (Overridden) (S\$)		6,800.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	21,220.02	4,800.00	16,420.02	77.38
+ GST 7.00/7.00% (S\$)	1,485.40	336.00	1,149.40	77.38
Nett Amount (S\$)	22,705.42	5,136.00	17,569.42	77.38

INSPECTION

Date of Assignment:	14/06/2022	Present Location:	Munich Autocare Pte Ltd (HQ)
Date Inspected:	15/06/2022	Inspected At:	Munich Autocare Pte Ltd (HQ) 60 Jalan Lam Huat, #07-43 Singapore 737869
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)

Parts: M1-MPV RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMH6127H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	651004703R-237103738R	*FRONT BONNET (WCP)	Bent	1,348.00 F	*1,348.00 F
2	1	R658479275R	*BONNET TOP BACK TRIM GS4 (WCP)	Serviceable	540.40 F	*- F
3	1	654000247R	*BONNET HINGE RH (WCP)	Repair	134.30 F	*- F
4	1	654013594R	*BONNET HINGE LH (WCP)	Repair	134.30 F	*- F
5	1	654704597R	*BONNET DAMPER LH (WCP)	Serviceable	112.20 F	*- F
6	1	654704597R	*BONNET DAMPER RH (WCP)	Serviceable	112.20 F	*- F
7	1	658408772R	*BONNET INSULATOR (WCP)	Serviceable	295.20 F	*- F
8	1	656016673R	*BONNET LOCK (WCP)	Repair	186.00 F	*- F
9	1	656220664R	*BONNET LOCK HANDLE (WCP)	Repair	75.10 F	*- F
10	1	623821034R	*RADIATOR GRILLE BLACK (WCP)	Cracked	265.00 F	*265.00 F
11	1	623855072R	*RADIATOR GRILLE CHROME MOULDING (WCP)	Cracked	346.80 F	*346.80 F
12	1	622561964R	*RADIATOR GRILLE (WCP)	Cracked	473.80 F	*473.80 F
13	1	620363937R	*FRONT RADIATOR GRILLE TOP GARNISH (WCP)	Buckled	458.40 F	*458.40 F
14	1	628905855R	*FRONT EMBLEM (WCP)	Dented	167.00 F	*167.00 F
15	1	253A49995R	*FRONT PARKING SENSOR x2 (WCP)	Serviceable	1,114.40 F	*- F
16	1	240704528R	*FRONT BUMPER SENSOR HARNESS WIRE (WCP)	Serviceable	183.10 F	*- F
17	1	R144614EA1B	*ENGINE INNER COOLER (WCP)	Punctured	898.10 F	*898.10 F
18	1	215586371R	*INTERCOOLER AIR DUCT (WCP)	Cracked	46.60 F	*46.60 F
19	1	620223972R	*FRONT BUMPER (WCP)	Buckled / Cracked	1,676.20 F	*1,461.70 F
20	1	620347326R	*FRONT BUMPER SIDE BRACKET RH (WCP)	Serviceable	154.60 F	*- F
21	1	620358403R	*FRONT BUMPER SIDE BRACKET LH (WCP)	Serviceable	154.60 F	*- F
22	1	622540901R	*FRONT BUMPER LOWER LIP (WCP)	Cracked	431.01 F	*431.01 F
23	1	622552918R	*FRONT BUMPER SIDE INNER BRACKET LH (WCP)	Repair	167.70 F	*- F
24	1	622541628R	*FRONT BUMPER SIDE INNER BRACKET RH (WCP)	Repair	167.70 F	*- F
25	1	625005785R	*FRONT SUPPORT PANEL (WCP)	Cracked	1,214.30 F	*1,214.00 F
26	1	R752106346R	*FRONT BUMPER REINFORCEMENT (WCP)	Repair	744.40 F	*- F
27	1	622907255R	*FRONT CENTRE BRACE BRACKET (WCP)	Serviceable	132.90 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1	620901789R620906523R	*FRONT BUMPER REINFORCEMENT LOWER GARNISH (WCP)	Cracked	239.10 F	*239.10 F
29	1	622353354R	*FRONT BUMPER UNDER DEFLECTOR (WCP)	Serviceable	617.80 F	*- F
30	1	269257264R	*FRONT HEADLAMP BRACKET RH (WCP)	Serviceable	160.70 F	*- F
31	1	269257264R	*FRONT HEADLAMP BRACKET LH (WCP)	Serviceable	160.70 F	*- F
32	1	261520089R	*FOGLAMP COVER LH (WCP)	Serviceable	261.40 F	*- F
33	1	261520089R	*FOGLAMP COVER RH (WCP)	Serviceable	261.40 F	*- F
34	1	261A24871R	*FOGLAMP CHROME MOULDING (WCP)	Serviceable	261.40 F	*- F
35	1	261500097R	*FOGLAMP RH (WCP)	Serviceable	106.50 F	*- F
36	1	260602165R	*HEADLAMP LH (WCP)	Serviceable	892.50 F	*- F
37	1	260101271R	*HEADLAMP RH (WCP)	Mtg Cracked	892.50 F	*892.50 F
<u>Supplementary #1</u>						
38	1	622568767R	*FRONT LOWER FLAP GUIDE INNER AIR DUCT (WCP)	Cracked	251.60 F	*251.60 F
39	1	7711428130	*COOLANT 5L (WCP)	Necessary	24.20 F	*24.20 F
40	1	214105169R	*RADIATOR (WCP)	Punctured	725.40 F	*725.40 F
41	1	921004063R	*AIRCON CONDENSER (WCP)	Punctured	930.00 F	*930.00 F
<u>Supplementary #2</u>						
42	1	214105169R	*RADIATOR ASSY (WCP)	Repeated	725.40 F	*- F
43	1	7711428130	*COOLANT 5L (WCP)	Repeated	24.20 F	*- F
F=Franchise part.						
					Sub Total (S\$)	18,269.11 10,173.21
					+ Margin on L,N Items 10.00/10.00% (S\$)	1,826.91 1,017.32
					Total Parts (S\$)	20,096.02 11,190.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIP (NECESSARY)	49.00	49.00
2	1	FRONT LICENSE PLATE WITH CASING (DENTED)	45.00	45.00
Sub Total (\$\$)			94.00	94.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANAL BEATING , REALIGN DISMANTLE FRONT BUMPER , SUPPORT PANEL , BONNET, AND ALL NECESSARY ETC	New	1,200.00	500.00
2	TO CHECK ELECTRICAL WIRING SYSTEM OF FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLAMP LH/RH & FOGLAMP LH/RH	New	80.00	20.00
3	TO DISMAITE & RENEW FRONT PARKING SENSOR	New	80.00	60.00
4	TO APPLY TUFF COASTING AND SPRAY ANTI RUST PROOFING REAR PORTION	New	120.00	0.00
5	TO PUTTY & RESPRAY PAINTING FRONT BUMPER, SUPPORT PANAL, BONNET ,AND ALL NECESSARY ETC	New	1,000.00	440.00
Supplementary #1				
Labour Items				
6	TO REMOVE/INSTALL A/COND CONDENSOR, RADIATOR COOLING SYSTEM TO REPLACE FRONT SUPPOORT PANEL AND DAMAGE AREA	New	180.00	100.00
7	TO CONDUCT RE-PROGRAME AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	250.00	150.00
8	TO REFILL A/COND GAS	New	120.00	0.00
Gross Labour Cost (\$\$)			3,030.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >