

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005674/KPA3Q2**Date:** 21/11/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0004693_01
Claimant Vehicle No :	SLS9281D	Insured Vehicle No :	SNC4822L
Date of Loss:	28/05/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0002838

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS9281D	Engine No:	2ZR8184229
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102071335
Reg. Date:	11/10/2017 (Man. Year: 2017)	Odometer:	321787 km
Colour:	Metallic Red		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,514.26	5,494.32	3,019.94	35.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,400.00	1,260.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,174.26	6,894.32	4,279.94	38.30
Approved Total (Overridden) (\$\$)		5,400.00		
Nett Amount (\$\$)	11,174.26	5,400.00	5,774.26	51.67
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	15/06/2022	
Date Inspected:	15/06/2022	Inspected At: Lian Her Motors (Ang Mo Kio) Blk 5038, Ang Mo Kio Industrial Park 2, #01-405 Singapore 569541
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2022)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS9281D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,320.60 FL	*1,320.60 FL
2	1		*REAR TAIL-GATE REFLECTOR	N/S Serviceable /O/SMtgCracked	1,244.48 FL	*612.40 FL
3	1		*REAR TAIL-GATE OUTER GARNISH	Mtg Cracked	891.20 FL	*745.60 FL
4	1		*REAR TAIL-GATE INNER LOCK	Dented	452.70 FL	*389.40 FL
5	1		*REAR TAIL-GATE EMBLEM -HYBRID	Necessary	48.90 FL	*48.90 FL
6	1		*REAR TAIL-GATE EMBLEM -C-HR	Necessary	45.80 FL	*45.80 FL
7	1		*REAR TAIL-GATE EMBLEM	Necessary	62.30 FL	*62.30 FL
8	1		*REAR BOOT RUBBER (50%)	Distorted / Dented	140.93 FS	*93.95 FS
9	1		*REAR BUMPER	Buckled	875.60 FL	*545.10 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	483.20 FL	*382.00 FL
11	2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	192.20 FL	*- FL
12	2		*REAR BUMPER REFLECTOR	Serviceable	130.20 FL	*- FL
13	1		*REAR BUMPER CENTRE GARNISH	Dented	75.20 FL	*75.20 FL
14	1		*REAR LOWER BUMPER	Cracked	487.10 FL	*487.10 FL
15	1		*REAR BUMPER TOW COVER	Dented	45.80 FL	*45.80 FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
17	1		*REAR ANTENNA	Serviceable	175.10 FL	*- FL
18	1		*REAR INNER LOCK SENSOR	Cracked	187.60 FL	*187.60 FL
19	2		*REAR FENDER ARCH GARNISH	Serviceable	330.40 FL	*- FL
20	1		*REAR END PANEL	Bent	725.70 FL	*725.70 FL
21	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	402.10 FL	*347.40 FL
22	1		*REAR SPARE TOOL COMPARTMENT	Cracked	320.10 FL	*320.10 FL
23	1		*REAR FENDER INNER TRIM BOARD	O/S Mtg Cracked	1,100.20 FL	*499.50 FL
24	1		*REAR EXHAUST SILENCER	Repair	855.90 FL	*- FL
25	1		*REAR EXHAUST SILENCER HEAT SHIELD	Serviceable	155.20 FL	*- FL
26	15		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
27	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
29	1		*REAR NO PLATE	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,203.71	7,204.45
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,689.45	1,710.13
Total Parts (\$\$)	8,514.26	5,494.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	1,200.00	600.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,200.00	600.00
3	CHECK AND RECONNECT WIRING	New	40.00	20.00
4	TO ANTI-RUST PROOFING	New	100.00	60.00
5	REMOVE/REFIT REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			2,660.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >