

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22005675/KVY3E2

**Date:** 20/06/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00066042200  
**Claimant Vehicle No :** SJV2659C **Insured Vehicle No :** SKM2282R  
Date of Loss: 10/06/2022 Nature of Claim: TP Claim No: SNM22D204125/C02/LEEPG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV2659C**  
Make & Model: KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A) Engine No: G4FC9H341516  
Reg. Date: 19/01/2010 (Man. Year: 2009) Chassis No: KNAFW411MA5175007  
Colour: Metallic Grey Odometer: 213247 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 235/45 R17 Rear Tyre Size: 235/45 R17  
Front Left Side: Bridgestone 2 mm Rear Left Side: Bridgestone 4 mm  
Front Right Side: Bridgestone 2 mm Rear Right Side: Firenza 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,589.20	1,193.20	396.00	24.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,260.00	490.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,339.20</b>	<b>2,453.20</b>	<b>886.00</b>	<b>26.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,339.20</b>	<b>1,950.00</b>	<b>1,389.20</b>	<b>41.60</b>

### INSPECTION

Date of Assignment: 15/06/2022

Date Inspected: 15/06/2022 Inspected At:

Ngs Motorsport Pte Ltd - Ang Mo Kio (HQ)  
Blk 10 Ang Mo Kio Ind Pk 2A, #02-01 AMK  
AutoPoint  
Singapore 568047

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 20 Jun 2022)

**Parts:** 143 KIA CERATO FORTE 1.6 SX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJV2659C)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Repair	407.50 FL	*- FL
2	1		*FRT DOOR LH	Bent	1,017.00 FL	*1,017.00 FL
3	14		*CLIPS, FENDER LINING	Not Necessary	70.00 FS	*- FS
4	1		*ROCKER PANEL	Bent	474.50 FL	*474.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

	<b>Sub Total (S\$)</b>	<b>1,969.00</b>	<b>1,491.50</b>
	<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	379.80	298.30
	<b>Total Parts (S\$)</b>	<b>1,589.20</b>	<b>1,193.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE FRT DAMAGED PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS, REPAIR / RESHAPE DENTED BODY PANEL. REPLACE / REPOSITION DAMAGED PARTS, REFIT ALIGN INTO REFIX ALL NECESSARY COMPONENTS / ATTACHMENT	New	800.00	600.00
2	TRANSFER DOOR MECHANISM	New	150.00	60.00
3	SPRAY PAINTING - FRT FENDER, FRT DOOR & ROCKER PANEL	New	800.00	600.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,750.00</b>
				<b>1,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >