

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122005678/EVCE2

Date: 30/06/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKW7008G

Insured Vehicle No : SBA12L

Date of Loss: 12/06/2022

Nature of Claim: TP

Claim No: CDMPG22001140

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW7008G**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD (A)

Engine No: HRA2190888A

Reg. Date: 12/11/2015 (Man. Year: 2015)

Chassis No: SJNFEAJ11U1489289

Colour: Grey

Odometer: 91041 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,954.30	7,963.50	990.80	11.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,840.00	680.00	26.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,474.30	9,803.50	1,670.80	14.56
Approved Total (Overridden) (S\$)		7,850.00		
(S\$)	11,474.30	7,850.00	3,624.30	31.59
+ GST 7.00/7.00% (S\$)	803.20	549.50	253.70	31.59
Nett Amount (S\$)	12,277.50	8,399.50	3,878.00	31.59

INSPECTION

Date of Assignment: 15/06/2022

Date Inspected: 15/06/2022 Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jun 2022)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW7008G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	3,706.00 FL	*3,300.00 FL
2	1		*BOOT LID EMBLEM QASHQAI	Necessary	114.00 FL	*80.00 FL
3	1		*BOOT LID LOGO BADGE	Not Necessary	85.00 FL	*- FL
4	1		*REAR WINDSCREEN MOULDING	Torn	198.00 FL	*100.00 FL
5	1		*REAR BUMPER	Broken	877.00 FL	*877.00 FL
6	2		*REAR BUMPER SIDE RETAINER LH / RH	Broken	98.00 FL	*98.00 FL
7	1		*REAR REINFORCEMENT	Bent	761.00 FL	*761.00 FL
8	1		*REAR BUMPER TOWING COVER	Broken	39.00 FL	*39.00 FL
9	2		*REAR BUMPER SIDE REFLECTOR LH / RH	Broken	138.00 FL	*69.00 FL
10	1		*REAR WHEEL ARCH GARNISH RH	Crushed	595.00 FL	*511.00 FL
11	1		*END PANEL	Dented	531.00 FL	*482.00 FL
12	1		*EXHAUST MUFFLER	Dented	578.00 FL	*578.00 FL
13	2		*EXHAUST MUFFLER RUBBER MOUNTING LH / RH	Not Necessary	84.00 FL	*- FL
14	1		*EXHAUST MUFFLER CENTER	Bent	982.00 FL	*829.00 FL
15	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
16	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
17	4		*REAR REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
19	1		*END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
20	1		*REAR BUMPER SPONGE	Broken	142.00 FL	*142.00 FL
21	2		*REAR BUMPER INNER TOP CLIPS	Broken	20.00 FL	*20.00 FL
22	1		*TAIL LAMP RH	Broken	347.00 FL	*347.00 FL
23	2		*REAR REFORCEMENT SIDE BRACKET BEAM LH / RH	Bent	282.00 FL	*282.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,912.00	8,815.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	957.70	851.50
Total Parts (\$\$)	8,954.30	7,963.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	900.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	600.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	100.00	30.00
5	TO REMOVE / REFIX / REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	100.00	100.00
7	TO REMOVE AND REPLACE EXHAUST MUFFLER	New	200.00	150.00
Gross Labour Cost (S\$)			2,520.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >