



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 902M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER RH	NOT NECESSARY	2,046.20	-
1	WHEEL ARCH REAR RH	NOT NECESSARY	220.10	-
1	QTR GLASS RH	NOT NECESSARY	404.90	-
1	FASTENER	NOT NECESSARY	8.20	-
1	FASTENER	NOT NECESSARY	2.80	-
1	FRONT DOOR RH	DENTED	1,213.40	1,213.40
1	WEATHERSTRIP DOOR FRT RH	NOT NECESSARY	106.40	-
10	FASTENER @\$3.40	NECESSARY	34.00	34.00
1	CHECKER RH FRT	NOT NECESSARY	72.50	-
12	GROMMET SCREW @\$3.00	NECESSARY	36.00	36.00
1	GROMMET SCREW	NECESSARY	3.80	3.80
1	UPPER HINGE RH FRT DOOR	NOT NECESSARY	44.10	-
1	LOWER HINGE RH FRT DOOR	NOT NECESSARY	37.80	-
5	FASTENER @\$7.20	NECESSARY	36.00	36.00
1	GARNISH LOWER DOOR FRT RH	CUT	224.00	224.00
1	GARNISH LOWER DOOR REAR RH	CUT	135.80	135.80
1	FRONT FENDER RH	DENTED	512.30	512.30
1	MUD GUARD RH FRT	NOT NECESSARY	116.60	-
5	RIVET @\$3.00	NECESSARY	15.00	15.00
1	WHEEL ARCH FRT RH	DEFORMED	186.70	186.70
1	WHEEL DISC-ALUMI	CUT	1,320.80	1,320.80
			6,777.40	3,717.80
<u>SPECIAL NETT ITEMS</u>				
3	CLIPS,GARNISH @\$12.30 (SN)	NECESSARY	36.90	36.90
1	SUNDRIES (SN)	NECESSARY	50.00	10.00
			86.90	46.90
<u>LABOUR</u>				
	REPLACE RHF FENDER ,RHF DOOR ,REPAIR RHR DOOR 11411.		4,800.00	1,980.00
	SPRAY FRT BUMPER ,RHF FENDER ,RHF DOOR ,RHR DOOR ,RHR FENDER ,REAR BUMPER.		4,000.00	2,520.00

Report Ref No. CS/SMO22005683/Ancq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT THE QUARTER GLASS AND CONDUCT WATER LEAK TEST.	NOT NECESSARY	280.00	-
	TO SUPPLY SEALER ON THE QUARTER GLASS .	NOT NECESSARY	80.00	-
	TO TRANSFER REVERSE SENSOR .	NOT NECESSARY	660.00	-
	TO TRANSFER THE DOOR MECHANISM .		330.00	330.00
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		120.00	120.00
	TO CHECK STEERING GEOMETRY & CONDCUT FUEL WHEEL ALIGNMENT.		560.00	280.00
	TO CARRY -OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOUUC).		250.00	80.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		300.00	180.00
			11,810.00	5,640.00
GRAND TOTAL			18,674.30	9,404.70
RECOMMENDED COST OF REPAIRS				9,404.70

Report Ref No. CS/SMO22005683/Ancq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.