

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22005687/AGNY3E2

Date: 25/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002057341		
Claimant Vehicle No :	SJU2783G	Insured Vehicle No :	SCH8182C		
Date of Loss:	13/06/2022	Nature of Claim:	TP	Claim No:	276606

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU2783G	Engine No:	2ZRA357350
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE200020232
Reg. Date:	25/11/2009 (Man. Year: 2009)	Odometer:	188650 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,912.77	3,249.67	2,663.10	45.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,490.00	1,410.00	48.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,812.77	4,739.67	4,073.10	46.22
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	8,812.77	3,800.00	5,012.77	56.88

INSPECTION

Date of Assignment:	14/06/2022	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	14/06/2022 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: XING GUO QIANG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU2783G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SUPPORT PANEL	Repair	1,069.50 FL	*- FL
2	1		*FRONT BUMPER	Distorted	530.10 FL	*530.10 FL
3	1		*FRONT BUMPER SIDE HOLDER	N/s Damaged	377.20 FL	*85.00 FL
4	1		*FRONT BUMPER LOWER LIP	Deformed	850.00 FL	*850.00 FL
5	1		*FRONT BUMPER LOWER LH SIDE GRILLE	Not Necessary	216.10 FL	*- FL
6	1		*FRONT BUMPER LOWER CENTRE GRILLE	Cut	277.00 FL	*277.00 FL
7	1		*FRONT GRILLE	Not Necessary	525.40 FL	*- FL
8	1		*FRONT LH HEADLAMP	Cracked	1,883.60 FL	*1,222.00 FL
9	1		*FRONT LH HEADLAMP LOWER PANEL	Not Necessary	189.70 FL	*- FL
10	1		*FRONT LH FENDER	Dented	933.60 FL	*645.00 FL
11	1		*FRONT LH FENDER INNER SHIELD	Torn	181.70 FL	*181.70 FL
12	1		*FRONT LH AIR DUCT	Cracked	333.70 FL	*186.00 FL
13	1		*FRONT HORN	Cracked	276.10 FL	*276.10 FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
15	1		*SET FRONT GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
16	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,823.70	4,312.90
- List Item Discount on L Items 25.00/25.00% (S\$)	1,910.93	1,063.23
Total Parts (S\$)	5,912.77	3,249.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	REMOVE & REINSTALL AIR CON FILL IN GAS	New	200.00	0.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
4	RESPRAY PAINTING	New	1,300.00	800.00
5	TO SPRAY TUFF COAT	New	150.00	60.00
Gross Labour Cost (\$)			2,900.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >