

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22005688/TNY3E2**Date:** 11/11/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000212
Claimant Vehicle No :	SHC3242M	Insured Vehicle No :	SLE3427P
Date of Loss:	11/06/2022	Nature of Claim:	TP
		Claim No:	M2203080

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3242M		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU047993
Reg. Date:	01/08/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVJU103778
Colour:	Blue	Odometer:	644629 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,664.56	1,346.96	317.60	19.08
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,495.56	1,987.96	507.60	20.34
Approved Total (Overridden) (\$\$)		1,450.00		
(\$\$)	2,495.56	1,450.00	1,045.56	41.90
+ GST 7.00/7.00% (\$\$)	174.69	101.50	73.19	41.90
Nett Amount (\$\$)	2,670.25	1,551.50	1,118.75	41.90

INSPECTION

Date of Assignment:	15/06/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	15/06/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC3242M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER LOWER MOULDING	Not Necessary	155.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	*- FL
7	1		*REAR BUMPER SMARTKEY ANTENNA	Not Necessary	40.50 FL	*- FL
8	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
9	1		*REVERSE SENSORS	Not Working	180.00 F	*180.00 F
10	1		*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,009.45	1,612.45
- List Item Discount on L Items 20.00/20.00% (\$\$)	344.89	265.49
Total Parts (\$\$)	1,664.56	1,346.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >