



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207312

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 25/11/2022
Reference CC6/CTI22005690/Rpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLR 591Z
Insured Veh. SNB 246G
Claim No. SNM22D203991/C02
Policy No. DMHCSNW00008462100
Accident Date 04/06/2022
Inspection Date 07/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22005690/Rpa3q2 Date: 25/11/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNB 246G	Veh. Inspected	SLR 591Z	
Policy No.	DMHCSNW00008462100	Coverage (\$)	0.00	
Claim No.	SNM22D203991/C02	Excess (\$)	0.00	
Assign From		Assign Date	07/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV 1.6I-S AWD	c.c	1600	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1GP3KC5HG206390	Colour	ORANGE	
Odometer	131400 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2022	Inspection Date	07/06/2022	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 591Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TORN	680.00	680.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	50.00	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	50.00	-
1	REAR BUMPER CORNER BRACKET RH - 57707AC	NOT NECESSARY	60.00	-
1	REAR BUMPER CORNER BRACKET LH - 57707AD	NOT NECESSARY	60.00	-
1	REAR BUMPER LOWER BRACKET - 57707N	NOT NECESSARY	60.00	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	50.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	50.00	-
1	REAR BUMPER TOW EYE COVER	SCRATCHED	60.00	60.00
1	REAR BUMPER PROTECTOR GUARD	NOT NECESSARY	580.00	-
1	REAR BUMPER FOGLAMP	SCRATCHED	220.00	220.00
1	REAR REINFORCEMENT	BENT	420.00	420.00
1	REAR TAIL LAMP RH	NOT NECESSARY	550.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	550.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	900.00	-
1	REAR TAILGATE LOCK	NOT NECESSARY	250.00	-
1	REAR TAILGATE RUBBER SEAL	NOT NECESSARY	160.00	-
1	REAR SUBARU EMBLEM	NOT NECESSARY	90.00	-
1	REAR AWD EMBLEM	NECESSARY	90.00	90.00
1	REAR XV EMBLEM	NECESSARY	60.00	60.00
1	REAR END PANEL	BENT	500.00	500.00
1	REAR END PANEL GARNISH	NOT NECESSARY	180.00	-
1	REAR EXHAUST	BENT	780.00	780.00
2	REAR EXHAUST RUBBER MOUNT @\$60.00	NECESSARY (1PC ONLY)	120.00	60.00
1	REAR FENDER SHIELD LH (ADDITIONAL)	CUT	120.00	120.00
1	REAR BUMPER SPACER PANEL LH (ADDITIONAL)	CUT	70.00	70.00
1	REAR BUMPER LOWER BRACKET LH (ADDITIONAL)	CRACKED	60.00	60.00
1	REAR BUMPER LOWER BRACKET RH (ADDITIONAL)	CRACKED	60.00	60.00

Report Ref No. CC6/CTI22005690/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST HEAT INSULATOR SHEET (ADDITIONAL)	BENT	140.00	140.00
	LESS 20% DISCOUNT		-	-674.00
			7,070.00	2,696.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
1	REAR LICENSE PLATE (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			280.00	-
	<u>LABOUR</u>			
	SPRAY PAINT REAR BUMPER, TAILGATE AND INNER PANEL.		1,000.00	600.00
	REPLACE & REFIT AFFECTED ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		1,000.00	500.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.	NOT NECESSARY	80.00	-
	REMOVE AND REPLACE REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	REMOVE AND REFIT REAR REVERSE SENSOR.		80.00	60.00
	REMOVE AND REFIT REAR EXHAUST PIPE AND SILENCER, RE-ALIGN.		80.00	60.00
	APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.		100.00	40.00
	CHECK AND RECTIFY ELECTRICAL WIRING.	NOT NECESSARY	30.00	-
	TO REPAIR SPARE TYRE SINK. (ADDITIONAL)		150.00	150.00
			2,640.00	1,410.00
GRAND TOTAL			9,990.00	4,106.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CC6/CTI22005690/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 591Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 591Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 591Z

RE-INSPECTION

