



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-297
DATE : 6-Jun-2022
POLICY NO. : DA MT/00806050
VEHICLE REG. NO. : SLR591Z
VEHICLE MAKE : SUBARU XV 1.6i-S AWD CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>turn</i>	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clip <i>in</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>? X NN</i>	1	\$ 50.00	\$ 50.00
4	Rear Bumper Retainer LH <i>X NN</i>	1	\$ 50.00	\$ 50.00
5	Rear Bumper Corner Bracket RH - 57707AC <i>? X NN</i>	1	\$ 60.00	\$ 60.00
6	Rear Bumper Corner Bracket LH - 57707AD <i>? X NN</i>	1	\$ 60.00	\$ 60.00
7	Rear Bumper Lower Bracket - 57707N <i>? X NN</i>	1	\$ 60.00	\$ 60.00
8	Rear Bumper Reflector RH <i>X NN</i>	1	\$ 50.00	\$ 50.00
9	Rear Bumper Reflector LH <i>X NN</i>	1	\$ 50.00	\$ 50.00
10	Rear Bumper Tow Eye Cover <i>scr</i>	1	\$ 60.00	\$ 60.00
11	Rear Bumper Protector Guard <i>X NN</i>	1	\$ 580.00	\$ 580.00
12	Rear Bumper Foglamp <i>scr</i>	1	\$ 220.00	\$ 220.00
13	Rear Reinforcement <i>st</i>	1	\$ 420.00	\$ 420.00
14	Rear Tail Lamp RH <i>X NN</i>	1	\$ 550.00	\$ 550.00
15	Rear Tail Lamp LH <i>X NN</i>	1	\$ 550.00	\$ 550.00
16	Rear Tailgate <i>repair</i>	1	\$ 900.00	\$ 900.00
17	Rear Tailgate Lock <i>X NN</i>	1	\$ 250.00	\$ 250.00
18	Rear Tailgate Rubber Seal <i>X NN</i>	1	\$ 160.00	\$ 160.00
19	Rear SUBARU Emblem <i>X NN</i>	1	\$ 90.00	\$ 90.00
20	Rear AWD Emblem <i>in</i>	1	\$ 90.00	\$ 90.00
21	Rear XV Emblem <i>in</i>	1	\$ 60.00	\$ 60.00
22	Rear End Panel <i>Repair st photo?</i>	1	\$ 500.00	\$ 500.00
23	Rear End Panel Garnish <i>? X NN</i>	1	\$ 180.00	\$ 180.00
24	Rear Exhaust <i>st</i>	1	\$ 780.00	\$ 780.00
25	Rear Exhaust Rubber Mount <i>in</i>	2	\$ 60.00	\$ 120.00
Total Spare Parts				\$ 6,620.00
SPECIAL NETT				
26	Rear Windscreen Sealant <i>X NN</i>	1	\$ 40.00	\$ 40.00
27	Rear License Plate <i>X NN</i>	1	\$ 40.00	\$ 40.00
28	Reverse Sensor <i>? X NN</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
LABOUR				
29	Spray Paint Rear Bumper, Tailgate and Inner Panel	1	\$ 1,000.00	\$ 1,000.00

2980
206
2384

0

600

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-297
DATE : 6-Jun-2022
POLICY NO. : DA MT/00806050
VEHICLE REG. NO. : SLR591Z
VEHICLE MAKE : SUBARU XV 1.6I-S AWD CVT
FOR SURVEYOR

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
30	Replace & Refit Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
31	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
32	Remove and Replace Rear Windscreen	1	\$ 120.00	\$ 120.00
33	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
34	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
35	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
36	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00
			Total Labour	\$ 2,490.00
			Amount Before Excess	\$ 9,390.00
			Add GST @ 7%	657.30
			Total Amount Payable	\$ 10,047.30

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2384

SLR-1260

Suppl-510

T-4154

20%

332320

48-\$3,300

Rashid

Hp 92010068

5 days

4/8

07/06/22 P1420

Resy after repair



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

Supplementary Estimate

ESTIMATE NO. : EST2206-297 (SUP)
DATE : 7-Jun-2022
POLICY NO. : DA MT/00806050
VEHICLE REG. NO. : SLR591Z
VEHICLE MAKE : SUBARU XV 1.6I-S AWD CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Fender Shield LH cut ✓	1	\$ 120.00	\$ 120.00
2	Rear Bumper Spacer Panel LH cut ✓	1	\$ 70.00	\$ 70.00
3	Rear Bumper Lower Bracket LH cra ✓	1	\$ 60.00	\$ 60.00
4	Rear Bumper Lower Bracket RH cra ✓	1	\$ 60.00	\$ 60.00
5	Exhaust Heat Insulator Sheet bt ✓	1	\$ 140.00	\$ 140.00
Total Spare Parts				\$ 450.00
<u>SPECIAL NETT</u>				
Total Special Nett				\$ -
<u>LABOUR</u>				
6	To Repair Spare Tyre Sink	1	\$ 150.00	\$ 150.00
Total Labour				\$ 150.00
Amount Before Excess				\$ 600.00
Add GST @ 7%				42.00
Total Amount Payable				\$ 642.00

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

450
20%
360

✓ 150