

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22005691/AVY3E2

**Date:** 17/08/2022

### REFERENCE

Insured/Claimant: RAINBOW FRAME WOOD SUPPLY Policy No: DMCG21010629  
Date of Loss: 11/06/2022 Nature of Claim: OD Claim No: CDMCG22001148

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK5359B**  
Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KDB043161  
Reg. Date: 31/08/2020 (Man. Year: 2020) Chassis No: JTFHT02P209990155  
Colour: Silver Odometer: 19867 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$80,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm  
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,415.00	1,326.60	88.40	6.25
Miscellaneous Items	135.00	80.00	55.00	40.74
Labour	238.50	238.50	0.00	0.00
Paintwork Labour	458.05	443.07	14.98	3.27
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,246.55</b>	<b>2,088.17</b>	<b>158.38</b>	<b>7.05</b>
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	2,246.55	1,588.17	658.38	29.31
<b>+ GST 7.00/7.00% (S\$)</b>	157.26	111.17	46.09	29.31
<b>Nett Amount (S\$)</b>	<b>2,403.81</b>	<b>1,699.34</b>	<b>704.47</b>	<b>29.31</b>

### INSPECTION

Date of Assignment: 15/06/2022 Present Location: Progressive Car Care Pte Ltd (HQ)  
Date Inspected: 04/07/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Estimated Period of Repair: 2.0 days Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Aug 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBK5359B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	<b>*BADGE HIACE</b> (WCP)	Necessary	20.00 F	*20.00 F
2	1	NA	<b>*BADGE TOYOTA</b> (WCP)	Necessary	30.00 F	*30.00 F
3	1	NA	<b>*BOOTLID/TAILGATE</b> (WCP)	Dented	670.00 F	*670.00 F
4	1	NA	<b>*HI-LEVEL BRAKELAMP</b> (WCP)	Cracked	70.00 F	*70.00 F
5	1	NA	<b>*NO-PLATE LAMP COVER</b> (WCP)	Not Necessary	100.00 F	*- F
6	1	NA	<b>*REAR SCREEN</b> (WCP)	Shorted	350.00 F	*350.00 F
7	1	NA	<b>*REAR WIPER ARM</b> (WCP)	Bent	40.00 F	*40.00 F
8	1	NA	<b>*REAR WIPER BLADE</b> (WCP)	Bent	35.00 F	*26.00 F
9	1	NA	<b>*RR BOOT INNER TRIM</b> (WCP)	Not Necessary	100.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>1,415.00</b>	<b>1,206.00</b>
<b>+ Margin on L,N Items 0.00/10.00% (\$\$)</b>	0.00	120.60
<b>Total Parts (\$\$)</b>	<b>1,415.00</b>	<b>1,326.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	RR NO PLATE (NOT NECESSARY)	35.00	0.00
2	1	RR STICKER - 70KM (NECESSARY)	20.00	10.00
3	1	RR STICKER - 8PAX (NECESSARY)	20.00	10.00
4	1	RR W/S SEALANT (NECESSARY)	40.00	40.00
5	1	RR W/S SPONGE TAPE (NECESSARY)	20.00	20.00
Sub Total (\$\$)			135.00	80.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	301.50	288.00
2	Total Paint Materials	New	156.55	155.07
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	238.50	238.50
Gross Labour Cost (\$\$)			696.55	681.57

Report was unsubmitted during this print-out.

< END OF ESTIMATES >