

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22005692/SQY3Q2**Date:** 01/09/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001016235
Claimant Vehicle No :	SGB566R	Insured Vehicle No :	SND7793L
Date of Loss:	28/05/2022	Nature of Claim:	TP
		Claim No:	202222005053FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB566R	Engine No:	39115456B38A15A
Make & Model:	BMW X1, 1.5 SDRIVE 18I (A)	Chassis No:	WBAJG120303G76704
Reg. Date:	31/10/2018 (Man. Year: 2018)	Odometer:	47067 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,479.95	532.15	947.80	64.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,004.00	663.00	24.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,146.95	2,536.15	1,610.80	38.84
+ GST 7.00/7.00% (S\$)	290.29	177.53	112.76	38.84
Nett Amount (S\$)	4,437.24	2,713.68	1,723.56	38.84

INSPECTION

Date of Assignment:	15/06/2022	Performance Motors Limited (Alexandra)
Date Inspected:	28/06/2022 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	3.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2022)
Parts:	M1-SUV	BMW X1 1.5 SDRIVE 18l (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGB566R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*REAR BUMPER TRIM PANEL BOTTOM (BASI)	Cut	208.45 FS	*208.45 FS
3	1		*REAR BUMPER PANEL PRIMED	Repair	907.80 FS	*- FS
4	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Cut	266.90 FS	*266.90 FS
5	12		*EXPANDING RIVET BLACK	Necessary	16.80 FS	*16.80 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,479.95	532.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	TO PAINTING REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
Gross Labour Cost (\$)			2,667.00	2,004.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >