



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
PUA CHIA HOW (PAN JIAHAO)	Cust No/Name /PUA CHIA HOW (PAN JIAHAO)
BLK 312C CLEMENTI AVENUE 4	Reg No/Reg Date SMN1225J / 06/08/201
#36-193	Date In/Mileage / 0
SINGAPORE 123312	Chassis No KNAPH81BSK5524332
Contact No Mobile: 91054231	Engine No D4HBJH205163
	Make/Model KIA/SORENTO 2.2 A D GT SR 4WD GDJI
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00081	Cash	07/06/2022/ 18:49	TLK	282 / Kevin Leong	52330				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE ON REAR BUMPER, REAR BUMPER LWR & AFFECTED AREA								1280.00
E PNT98000	PAINT WORK ON REAR BUMPER & REAR RH FENDER								1650.00
E PNT88000	REMOE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR								150.00
M SUNDRY	PERFORM RUST PREVENTION								50.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA								50.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								150.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
M SUNDRY	SUNDRIES								50.00
M GARNISH ASSY-FNDR SIDE,RH					1.00	109.00	00.00	109.00	
M COVER-RR BUMPER,UPR					1.00	632.00	00.00	632.00	
M COVER-RR BUMPER LWR					1.00	594.00	00.00	594.00	
M SKID PLATE-RR BUMPER					1.00	103.00	00.00	103.00	
M BRACKET ASSY-RR BUMPER SIDE,RH					1.00	30.00	00.00	30.00	
M COVER-BLANKING RR FOG,RH					1.00	44.00	00.00	44.00	
M LAMP ASSY-REAR FOG & R/REFL,RH					1.00	134.00	00.00	134.00	
M RAIL ASSY-REAR BUMPER					1.00	341.00	00.00	341.00	

Confirm &amp; accepted by

Net 5,647.00  
 7% GST on 5647.00 395.29  
**Total Payable 6,042.29**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.