



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1562Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	OS SIDE GLASS R6	CRACKED	765.60	765.60
1	OS SIDE FUEL TANK DOOR	BENT	520.00	520.00
1	OS SIDE SMALL PANEL ABV FUEL TANK DOOR	BENT	149.60	149.60
5	SEALANT	NECESSARY	350.00	350.00
			1,785.20	1,785.20
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE :- } - ITEMS NO. 1-4. }		1,950.00	1,950.00
	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :- } - OS REAR BODY PANEL }		650.00	-
	SPRAY PAINTING :- - OS SIDE FUEL TANK DOOR - OS SIDE SMALL PANEL ABV FUEL TANK DOOR - OS REAR BODY PANEL		1,920.00	1,280.00
			4,520.00	3,230.00
GRAND TOTAL			6,305.20	5,015.20
RECOMMENDED COST OF REPAIRS				5,015.20

Report Ref No. CS/SMR22005702/Rncm4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.