

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL	R	ef:	CS3/SMO22005705/Kty3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Da	ate:	20/06/2022	
			C	ode:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKP 3998L	Veh. Inspected		FBK 8002K	
	Policy No.	SKP3998L	Coverage (\$)		0.00	
	Claim No.	CMTD2202072/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		15/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZN150	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	ME1RG1613F2001635	Colour		BLACK	
	Odometer	107818 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80 R17	MICHELIN		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70 R17	MICHELIN		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.					
5.	5. General Information					
	Accident Date	13/06/2022	Inspect Date / Tir	me	16/06/2022 (10:05 AM)	
	Survey held at	TUNE IN MOTOR	•			
	BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMO22005705/Kty3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser