



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Invoice Date: 18 August 2022

Vehicle Reg No: SMZ 5903 X

Model/Type: B.M.W. 640I GRAN COUPE

Accident Date: 31 May 2022

Owner: LIN WEI

Address: C/o: Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

RE: FINAL REPAIR BILL FOR THE VEHICLE AS MENTIONED ABOVE

(LUMP SUM REPAIR)

\$ 6,000.00

Singapore Dollars: SIX THOUSAND DOLLARS ONLY

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647.Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2022-215
Invoice No: TP/ZA/2022-215
Vehicle No: SMZ5903X
Attn: LIN WEI
Company: ZOOM AUTOWERKS
Address: Blk 15 Kaki Bukit Road 4.#01-53, Bartley Biz Centre . Singapore 417808

Date 18 August 2022

Invoice

Surveyor Fee:	S\$555
Re-inspection Fee:	S\$80
Transport:	S\$60
Photographs:	S\$50/- (@ \$1 per photo, total 50 photos)
Total:	S\$575

Surveyor:
Signature:
Date:



18 August 2022

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : LIN WEI
C/O ZOOM AUTOWERKS
Blk 15 Kaki Bukit Road 4, #01-53, Bartley Centre.
Singapore 417808

Date : 18 August 2022
Our Ref : WG/TP/2022-215

REFERENCE PARTICULARS

Date of Accident : 31 May 2022
Date of Inspection : 13 July 2022

Type of Inspection : Third Party Claim
Date of Re-Inspn : 15 July 2022

VEHICLE PARTICULARS

Registration No : SMZ5903X
Make : B.M.W.
Model : 640I GRAN COUPE 4DR SR LED DSC NAV HUD
Year : 2012

Engine No : 07588211N55B30A
Chassis No : WBA6A02030DZ10459
Odometer : 118810km
Colour : Beige

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near side	: Michelin	275/30ZR20	5 mm
Front Off Side	: Michelin	275/30ZR20	5 mm
Rear Near Side	: Michelin	275/30ZR20	5 mm
Rear off Side	: Michelin	275/30ZR20	5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front portions..
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,000.00** nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Fifty (50) photographs depicting damage to the vehicle.

Inspection conducted at : ZOOM AUTOWERKS
Blk 15 Kaki Bukit Road 4, #01-53, Bartley Centre. Singapore 417808

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO : SMZ5903X
MODEL : 640I GRAN COUPE 4DR SR LED DSC NAV HUD

Our Ref : WG/TP/2022-215

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
01	FRONT BUMPER	1	CRACKED	\$ 2,290.00	\$ 2,290.00
02	FRONT BUMPER RETAINER LH	1	NECESSARY	\$ 176.00	\$ 176.00
03	FRONT BUMPER RETAINER RH	1	NECESSARY	\$ 176.00	\$ 176.00
04	FRONT BUMPER INNER GUIDE	1	NOT NECESSARY	\$ 392.00	\$ -
05	FRONT BUMPER SPONGE	1	CRACKED	\$ 195.00	\$ 195.00
06	FRONT BUMPER REINFORCEMENT	1	NOT NECESSARY	\$ 1,590.00	\$ -
07	FRONT BUMPER LOGO	1	NECESSARY	\$ 188.00	\$ 188.00
08	FRONT INNER AIR GUIDE RH	1	DEFORMED	\$ 276.00	\$ 276.00
09	FRONT INNER AIR GUIDE LH	1	DEFORMED	\$ 276.00	\$ 276.00
10	FRONT BUMPER GRILLE LH	1	CRACKED	\$ 598.00	\$ 598.00
11	FRONT BUMPER GRILLE RH	1	MISSING	\$ 598.00	\$ 598.00
12	FRONT BUMPER LOWER GRILLE	1	NOT NECESSARY	\$ 210.00	\$ -
13	FRONT BUMPER LOWER GRILLE LH	1	NOT NECESSARY	\$ 155.00	\$ -
14	FRONT BUMPER LOWER GRILLE RH	1	NOT NECESSARY	\$ 155.00	\$ -
15	FRONT DISTANCE SENSOR	4	MALFUCNTION	\$ 1,476.00	\$ 738.00
16	FRONT HEADLAMP LH	1	NOT NECESSARY	\$ 3,870.00	\$ -
17	FRONT HEADLAMP RH	1	NOT NECESSARY	\$ 3,870.00	\$ -
				\$ 16,491.00	\$ 5,511.00
				Less 10%	\$ 1,649.20
					\$ 14,841.80
					\$ 4,959.90

B) S/NETT ITEM

18	FRONT BUMPER CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00
19	FROTN GRILLE CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00
20	FRONT NUMBER PLATE	1	GRAZED	\$ 100.00	\$ 90.00
				\$ 180.00	\$ 150.00

Parts Total :

\$ 15,021.80	\$ 5,109.90
--------------	-------------

C) LABOUR CHARGES & MISC

21	CHECK FRONT WIRING AND LIGHTNING SYSTEM			\$ 100.00	\$ 90.00
22	DIAGNOIS CHECK CLEAR FAULT CODE AND RESET FRONT HEADLAMP			\$ 600.00	\$ 500.00
23	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS			\$ 900.00	\$ 800.00
24	SPRAY PAINTING ON AFFECTED AEREAS			\$ 1,000.00	\$ 900.00
25	APPLY ANTI RUST ON AFFECTED AREAS			\$ 120.00	\$ 100.00
				\$ 2,720.00	\$ 2,390.00

Labour Total :

\$ 2,720.00	\$ 2,390.00
-------------	-------------

Total Parts and Laboure :

\$ 17,741.80	\$ 7,499.90
--------------	-------------

FINAL LUMP SUM ADJUSTMENT

\$ 6,000.00

POINT OF IMPACT

The impact was confined to the front portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS


We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **SS6,000.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

WG APPRAISAL SERVICES



Winson Goh
Automotive Appraiser