



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 5903X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRACKED	2,290.00	2,290.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	176.00	-
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	176.00	-
1	FRONT BUMPER INNER GUIDE	NOT NECESSARY	392.00	-
1	FRONT BUMPER SPONGE	TORN	195.00	195.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	1,590.00	-
1	FRONT BUMPER LOGO	NECESSARY	188.00	188.00
1	FRONT INNER AIR GUIDE RH	DEFORMED	276.00	276.00
1	FRONT INNER AIR GUIDE LH	DEFORMED	276.00	276.00
1	FRONT BUMPER GRILLE LH	CRACKED	598.00	598.00
1	FRONT BUMPER GRILLE RH	MISSING	598.00	598.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	210.00	-
1	FRONT BUMPER LOWER GRILLE LH	NOT NECESSARY	155.00	-
1	FRONT BUMPER LOWER GRILLE RH	NOT NECESSARY	155.00	-
4	FRONT DISTANCE SENSOR	SERVICEABLE	1,476.00	-
1	FRONT HEADLAMP LH	NOT NECESSARY	3,870.00	-
1	FRONT HEADLAMP RH	NOT NECESSARY	3,870.00	-
	LESS 10% DISCOUNT		-1,649.10	-442.10
			14,841.90	3,978.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	40.00	30.00
1	FRONT NUMBER PLATE (SN)	GRAZED	100.00	40.00
			180.00	100.00
<b><u>LABOUR</u></b>				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		100.00	30.00
	DIAGNOIS CHECK CLEAR FAULT CODE AND RESET FRONT HEADLAMP.	NOT NECESSARY	600.00	-
	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS.		900.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	500.00

Report Ref No. CS3/SMR22005707/Ucy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
			2,720.00	930.00
GRAND TOTAL			17,741.90	5,008.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS3/SMR22005707/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.