

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005708/ANCE2

Date: 15/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00143332101
Claimant Vehicle No: GBL3564H Insured Vehicle No: GBF5230P
Date of Loss: 11/06/2022 Nature of Claim: TP Claim No: SNM22D204148C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL3564H**
Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 1KDB088108
Reg. Date: 21/06/2021 (Man. Year: 2021) Chassis No: JTFAT35YX0K216641
Colour: Silver Odometer: 33760 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12C
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,805.55	1,832.66	4,972.89	73.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	920.00	2,290.00	71.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,015.55	2,752.66	7,262.89	72.52
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	10,015.55	2,200.00	7,815.55	78.03

INSPECTION

Date of Assignment: 15/06/2022
Date Inspected: 15/06/2022 Inspected At: Cheng Motor Work Company (HQ)
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jul 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL3564H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,339.25 F	*1,339.25 FL
2	1		*TAILGATE HINGE (4 Pcs)	Dented (2 Pcs only)	260.00 F	*130.00 FL
3	2		*TAILGATE HANDLE	Not Necessary	150.00 F	*- FL
4	1		*TAILLAMP	O/s Cut	756.40 F	*255.00 FL
5	2		*TAILLAMP PANEL	Not Necessary	556.60 F	*- FL
6	2		*SIDE GATE LOCK	Not Necessary	540.00 F	*- FL
7	1		*SIDE GATE STOPPED	N/s Missing	77.00 F	*38.50 FL
8	1		*REAR EXHAUST PIPE	Not Necessary	789.10 F	*- FL
9	1		*REAR END PANEL	Repair	979.20 F	*- FL
10	1		*NUMBER PLATE PANEL	Not Necessary	187.90 F	*- FL
11	1		*NUMBER PLATE LAMP	Not Necessary	87.90 F	*- FL
12	1		*SPARE TYRE HOLDER ASSY	Not Necessary	378.20 F	*- FL
13	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
14	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
15	1		*REVERSE SENSOR BRACKET	Bent	60.00 FS	*30.00 FS
16	1		*70KM STICKER	Necessary	20.00 FS	*10.00 FS
17	1		*TAILGATE EMBLEM TOYOTA STICKER	Necessary	253.40 FS	*180.00 FS
18	1		*TAILGATE EMBLEM DYNA STICKER	Necessary	50.60 FS	*50.60 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,805.55	2,273.35
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	440.69
Total Parts (\$\$)	6,805.55	1,832.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR KNOCKING,WELDING,CUTTING,REPAIRING AND REPLACEMENT OF PARTS	New	1,200.00	400.00
2	TO SPRAY PAINT ON THE DAMAGE PARTS	New	800.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	150.00	40.00
4	TO REMOVE/RENEW REAR EXHAUST	New	100.00	0.00
5	TO LIFT UP REAR BODY FOR KNOCKING CROSS BEAM	New	800.00	0.00
6	TO REMOVE/RENEW REVERSE SENSOR	New	100.00	50.00
7	TO CHECK WIRING	New	60.00	30.00
Gross Labour Cost (\$\$)			3,210.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >