8/18/22, 1:17 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005710/ANCQ2

18/08/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMHCSNA00008142202

Claimant Vehicle No:

SLZ1402M

Insured Vehicle No:

SML8755K

Date of Loss:

13/06/2022

Nature of Claim: TP

Claim

Chassis No:

SNM22D204151/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLZ1402M Reg No:

AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Make & Model:

Engine No: CHZ435247

Reg. Date: 24/04/2018 (Man. Year: 2018)

WAUZZZ8V6J1055658 Odometer: 170707 km

Colour: Grey **Engine Capacity:** 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,517.49	4,182.79	4,334.70	50.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	920.00	1,120.00	54.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,557.49	5,102.79	5,454.70	51.67
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	10,557.49	4,000.00	6,557.49	62.11
+ GST 7.00/7.00% (S\$)	739.02	280.00	459.02	62.11
Nett Amount (S\$)	11,296.51	4,280.00	7,016.51	62.11

INSPECTION

Date of Assignment: 15/06/2022

N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT Date Inspected: 15/06/2022 Inspected At: **AUTOHUB**

Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: **ADRIAN LING** Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Aug 2022)

Parts: 144 AUDI A3 999cc SEDAN TFSI S TRONIC (LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ1402M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,800.72 FL	*1,800.72 FL
2	1		*REAR BUMPER CENTER BRACKET	Cracked	399.70 FL	*399.70 FL
3	2		*REAR BUMPER LOWER BRACKET L/R	Cracked	223.54 FL	*223.54 FL
4	1		*REAR BUMPER LOWER LID	Deformed	688.77 FL	*348.00 FL
5	2		*REAR BUMPER REFLECTOR L/R	Cracked	267.92 FL	*267.92 FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	699.89 FL	*699.89 FL
7	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	935.60 FL	*467.80 FL
8	4		*REAR BUMPER REVERSE SENSOR O RING	Necessary	72.68 FL	*72.68 FL
9	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	999.60 FL	*-FL
10	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	279.58 FL	*- FL
11	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	133.75 FL	*-FL
12	1		*REAR END PANEL	Repair	1,388.69 FL	*- FL
13	1		*REAR END PANEL ANTENNA SENSOR	Cracked	333.96 FL	*333.96 FL
14	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	688.75 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	8,963.15	4,644.21
- List Item Discount on L Items 5.00/10.00% (S\$)				445.66	461.42	

Report was unsubmitted during this print-out.

Total Parts (S\$) 8,517.49

4,182.79

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	100.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	400.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	300.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
7	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	0.00
	Gross Labour Cost (S\$)		2,040.00	920.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >