

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005711/GVY3Q2**Date:** 23/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00071012100

Claimant Vehicle No : SKJ929M **Insured Vehicle No :** GBL3484E

Date of Loss: 09/06/2022 Nature of Claim: TP Claim No: SNM22D204071/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ929M**

Make & Model: TOYOTA VELLFIRE, 2.5 CVT (A) Engine No: 2ARJ243885

Reg. Date: 26/11/2019 (Man. Year: 2019) Chassis No: AGH300236378

Colour: White Odometer: 102022 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,205.00	4,765.50	3,439.50	41.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	1,310.00	4,140.00	75.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,655.00	6,075.50	7,579.50	55.51
+ GST 7.00/7.00% (\$\$)	955.85	425.29	530.56	55.51
Nett Amount (\$\$)	14,610.85	6,500.79	8,110.06	55.51

INSPECTION

Date of Assignment: 15/06/2022

Date Inspected: 12/07/2022 Inspected At: BLK 3007 UBI ROAD 1 #01-450
SINGAPORE 408700
Repairer: Jack Cars Enterprise Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ929M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,800.00 FL	*1,217.00 FL
2	1		*REAR BUMPER INNER BRACKET	Not Necessary	70.00 FL	*- FL
3	1		*REAR BOOT	Buckled	2,300.00 FL	*1,718.00 FL
4	1		*REAR BOOT INNER COVER	Not Necessary	380.00 FL	*- FL
5	1		*REAR BOOT WEATHERSTRIP	Twisted	320.00 FL	*320.00 FL
6	1		*REAR BOOT CHROME GARNISH	Scratched	210.00 FL	*210.00 FL
7	1		*REAR END PANEL	Repair	550.00 FL	*- FL
8	1		*REAR END PANEL TOP COVER	Deformed	180.00 FL	*180.00 FL
9	1		*RIGHT TAILGATE LAMP -INNER	Cracked	930.00 FL	*930.00 FL
10	1		*RIGHT TAILGATE LAMP -OUTER	Not Necessary	650.00 FL	*- FL
11	1		*LEFT TAILGATE LAMP -INNER	Cracked	930.00 FL	*930.00 FL
12	1		*LEFT TAILGATE LAMP -OUTER	Not Necessary	650.00 FL	*- FL
13	1		*BOOT LOCK -UPPER	Not Necessary	320.00 FL	*- FL
14	1		*BOOT LOCK -LOWER	Not Necessary	180.00 FL	*- FL
15	1		*TOW HOOK COVER	Deformed	90.00 FL	*45.00 FL
16	1		*REAR NUMBER PLATE & COVER	Bent	65.00 FS	*45.00 FS
17	1		*CLIPS ,RIVETS & SCREWS	Necessary	150.00 FS	*50.00 FS
18	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
19	1		*VELLFIRE EMBLEM	Necessary	150.00 FS	*88.00 FS
20	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
21	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
22	1		*WINDSCREEN WEATHERSTRIP	Necessary	210.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,595.00	6,153.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,390.00	1,387.50
Total Parts (\$\$)	8,205.00	4,765.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	600.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS KNOCK ,JACK ,WELD ,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	2,500.00	400.00
3	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	New	350.00	30.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS }	New	220.00	60.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY }	New	280.00	0.00
6	TO REMOVE & REINSTALL SENSORS	New	200.00	40.00
7	TO REMOVE & REINSTALL REAR WINDSCREEN	New	200.00	120.00
8	ANTI RUST TREATMENT	New	200.00	60.00
Gross Labour Cost (\$\$)			5,450.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >