

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : D21002039MFBP Date: 21st Mar 2023

Our Ref : CS/FCI22005712/Ecy3e2

M/s Ms First Capital Insurance Ltd

36 Robinson Road #16-01 City House Singapore 068877 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SBS 6403H ACCIDENT ON 11/07/2021

Instruction was received to inspect the vehicle Reg. No. SBS 6403H. The inspection was conducted on 16/06/2022 at the premises of M/s Tower Transit Singapore Pte Ltd, 21 Bulim Drive, Singapore 648170.

The following vehicle information was recorded:

Registration Number : SBS 6403H

Make/Model : Mercedes Benz Citaro O530

Year of Registration : 2013 Body Colour : Green

Chassis Number : WEB62808323125102

Engine Capacity : 6378 cc Speedometer Reading : Not Available

The vehicle sustained damages at the o/s, n/s body, front and rear portion. The Estimated repair cost of such vehicle is S\$267,784.63 (Sin Dollars: Two Hundred Sixty-Seven Thousand Seven Hundred Eighty-Four and Sixty-Three cents only.) (Include check items S\$173,421.36Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**Total Loss**".

(a) If the vehicle to be "Total Loss"

| Net Book Value | S\$ | 218,980.56 |
|----------------|-----|------------|
| | | |

S\$ 218,980.56

Less: Excess (S\$ 50,000.00)

Nett Liability S\$ 168,980.56

(b) If the vehicle to be "Repair"

| Repair Cost (Est) | S\$ | 267,784.63 |
|-------------------|-----|------------|
|-------------------|-----|------------|

(Include check items S\$173,421.36Nett)

Less: Excess (S\$ 50,000.00)

Nett Liabilibity S\$ 217,784.63

(a) - (b) = (S\$ 48,804.07)

The amount of estimated saving of S\$48,804.07 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

1

CHEN TSUE YEE
Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.