

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22005713/ANY3Q2**Date:** 16/08/2022REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SJT3123K**Insured Vehicle No :** SMX27T

Date of Loss: 14/06/2022

Nature of Claim: TP

Claim No: DMPC2200243H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJT3123K**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 1NZX972971

Reg. Date: 01/10/2009 (Man. Year: 2009)

Chassis No: MR053HY9305131333

Colour: Red

Odometer: 238625 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16

Rear Tyre Size: 195/55 R16

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,393.55	2,466.17	1,927.38	43.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	1,340.00	1,700.00	55.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,433.55	3,806.17	3,627.38	48.80
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	7,433.55	3,000.00	4,433.55	59.64
+ GST 7.00/7.00% (\$\$)	520.35	210.00	310.35	59.64
Nett Amount (\$\$)	7,953.90	3,210.00	4,743.90	59.64

INSPECTION

Date of Assignment: 15/06/2022

Date Inspected: 16/06/2022 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM
Inspection Centre
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT3123K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	688.30 FL	*- FL
2	1		*BOOT LID LOGO	Necessary	90.00 FL	*58.00 FL
3	1		*BOOT LID EMBLEM VIOS	Necessary	60.00 FL	*60.00 FL
4	1		*BOOT LID EMBLEM SPORT	Necessary	55.00 FL	*55.00 FL
5	1		*BOOT LID EMBLEM E	Necessary	46.50 FL	*46.50 FL
6	1		*BOOT LID TOP LOCK	Not Necessary	135.00 FL	*- FL
7	1		*BOOT LID WEATHERSTRIP	Not Necessary	213.00 FL	*- FL
8	2		*BOOT LID HINGE	Not Necessary	226.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	580.20 FL	*580.20 FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	109.00 FL	*109.00 FL
11	2		*REAR BUMPER BRACKET	Not Necessary	126.00 FL	*- FL
12	1		*TAIL LAMP	N/S Cracked	732.40 FL	*366.20 FL
13	2		*TAIL LAMP INNER RUBBER	Necessary	110.00 FL	*20.00 FL
14	1		*REAR END PANEL	Dented	669.00 FL	*669.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	135.00 FL	*135.00 FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	1		*SET REAR BUMPER CLIPS	Necessary	22.00 FS	*22.00 FS
18	1		*REAR BUMPER LOWER LID	Deformed	1,000.00 FS	*600.00 FS
19	1		*REAR END PANEL INSULATION SEAL	Necessary	100.00 FS	*60.00 FS
20	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
21	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,387.40	2,990.90
- List Item Discount on L Items 25.00/25.00% (\$)	993.85	524.73
Total Parts (\$)	4,393.55	2,466.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,KNOCK ,GRAZA ADJUST REPLACE NEW PARTS	New	1,200.00	600.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX ADJACENT PANELS	New	1,200.00	600.00
3	TO SPRAY TUFF COAT AND RUST RPOOF ADJACENT PANELS	New	250.00	60.00
4	WIRING BULB CHECKING	New	120.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
6	TRANSFER BOOT LID MECHANISM	New	150.00	0.00
Gross Labour Cost (\$\$)			3,040.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >