

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM22005714/Rvcm4		
	8 SHENTON WAY SINGAPORE 0688		Date:	21/06/2022		
	ATTN: LOH CYNTH	AIF		Code:	ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SHC 5533K	Veh. Inspected	ł	GBH 6198H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M044AS	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		16/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV350 P.V 2.5 MT	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JN1MC2E26Z0008919	Colour		GREY	
	Odometer	141023 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	OHTSU		6 mm	
	L/H Front Tyre	195 R15	OHTSU		6 mm	
	R/H Rear Tyre	195 R15	OHTSU		6 mm	
	L/H Rear Tyre	195 R15	OHTSU		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	FRONT PORTIO	N.			
5. General Information						
	Accident Date	15/06/2022	Inspect Date /	Time	16/06/2022 (12:35 PM)	
	Survey held at	JSSPRAYWERKS				
		5035 ANG MO KIO INDUSTRIAL PARK 2, #01-355, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
	b. Estimate Days of Repair					
5b.		Estimate	Days of Repair			

Report Ref No. CS3/ASM22005714/Rvcm4

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

RECO Auto Consultant OAE Licensed American

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$