

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22005717/DQY3M4**Date:** 29/07/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001401006
Claimant Vehicle No :	ER925C	Insured Vehicle No :	SKS778J
Date of Loss:	12/06/2022	Nature of Claim:	TP
		Claim No:	202222005182

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	ER925C	Engine No:	R18A12801249
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68408S201242
Reg. Date:	28/01/2008 (Man. Year: 2007)	Odometer:	252475 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,442.96	2,779.48	663.48	19.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,155.00	2,505.00	1,650.00	39.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,597.96	5,284.48	2,313.48	30.45
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	7,597.96	4,200.00	3,397.96	44.72
+ GST 7.00/7.00% (S\$)	531.86	294.00	237.86	44.72
Nett Amount (S\$)	8,129.82	4,494.00	3,635.82	44.72

INSPECTION

Date of Assignment:	15/06/2022	Inspected At:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839
Date Inspected:	16/06/2022		
Estimated Period of Repair:	5.0 days		

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2022)
Parts: M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for ER925C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER MOULDING	Necessary	41.80 FL	*41.80 FL
2	1		*REAR BOOT	Buckled	991.10 FL	*991.10 FL
3	2		*REAR BOOT HINGE L&R	Not Necessary	105.20 FL	*- FL
4	1		*REAR BOOT LOCK	Damaged	128.20 FL	*128.20 FL
5	1		*REAR BOOT LOWER CATCH	Repair	31.60 FL	*- FL
6	1		*REAR BOOT DAMPER RH	Not Necessary	132.90 FL	*- FL
7	1		*REAR BOOT INNER FINISHER	Deformed	170.30 FL	*170.30 FL
8	1		*REAR LAMP ASSY RH	Broken	425.90 FL	*425.90 FL
9	1		*REAR BUMPER	Dented	704.90 FL	*704.90 FL
10	1		*REAR BUMPER SIDE RETAINER	Serviceable	23.60 FL	*- FL
11	1		*REAR BUMPER INNER END PANEL	Dented	346.20 FL	*346.20 FL
12	1		*REAR BOOT RUBBER	Deformed	148.20 FL	*148.20 FL
13	1		*REAR END PANEL INNER GARNISH CENTRE	Deformed	146.50 FL	*146.50 FL
14	1		*REAR FENDER INNER FINISHER RH	Serviceable	275.50 FL	*- FL
15	1		*REAR BOOT HONDA STREAM EMBLEM	Necessary	38.50 FL	*38.50 FL
16	1		*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	204.30 FL	*- FL
17	1		*REAR BOOT H EMBLEM	Necessary	26.50 FL	*26.50 FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*45.00 FS
19	1		*REAR BUMPER PARKING SENSOR	Damaged	200.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,231.20	3,413.10
- List Item Discount on L Items 20.00/20.00% (S\$)	788.24	633.62
Total Parts (S\$)	3,442.96	2,779.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL REAR WINDSCREEN	New	120.00	120.00
2	CAR-O-LINER	New	350.00	0.00
3	SPRAY PAINTING PEARL WHITE	New	1,800.00	1,200.00
4	CHECK WIRING SYSTEM	New	25.00	25.00
5	RENEW PARKING SENSOR	New	80.00	40.00
6	REMOVE & INSTALL REAR BOOT CARPET	New	100.00	60.00
7	REMOVE & INSTALL R/BOOT, R/LAMP, R/BUMPER, CUT OUT & RENEW END PANEL, KNOCK R/FENDER RH, SPARE TYRE PANEL AND RESTRAIGHTEN BODY & CHASSIS	New	1,500.00	1,000.00
8	REMOVE & INSTALL REAR EXHAUST BOX AND KNOCKING AIR BAG CONTROL UNIT	New	180.00	60.00
			Gross Labour Cost (\$)	4,155.00
				2,505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >