



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 3144Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT FENDER (CONSISTENT)	NOT NECESSARY	285.00	-
1	TOP FAIRING (CONSISTENT)	CRACKED	380.00	220.00
1	TOP FAIRING INNER COVER (CONSISTENT)	DEFORMED	220.00	190.00
2	FRONT SIDE COVER (CONSISTENT)	CRACKED	780.00	500.00
2	FRONT SIDE INNER COVER (CONSISTENT)	N/S DEFORMED/ O/S CRACKED	660.00	420.00
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	520.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	420.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	78.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	58.00	-
1	SET SIDE MIRRORS (CONSISTENT)	CUT	180.00	120.00
1	SET HANDLE-BAR (CONSISTENT)	BENT	280.00	180.00
1	SET HANDLE-BAR ENDS (CONSISTENT)	CUT	98.00	50.00
1	SET HANDLE GRIP (CONSISTENT)	CUT	80.00	60.00
1	HEADLAMP (CONSISTENT)	CRACKED	750.00	300.00
1	LAMP STAY (CONSISTENT)	BENT	480.00	190.00
1	CLUTCH LEVER (CONSISTENT)	CUT	78.00	40.00
1	BRAKE LEVER (CONSISTENT)	CUT	78.00	40.00
1	FUEL TANK (CONSISTENT)	TO REPAIR SEE LABOUR	950.00	-
1	SET FRONT SIGNALS (CONSISTENT)	BROKEN	252.00	190.00
1	SET FRONT FOOTREST (CONSISTENT)	DENTED	180.00	120.00
1	SET FRONT FOOTREST BRACKET (CONSISTENT)	BROKEN	580.00	250.00
1	BRAKE PEDAL (CONSISTENT)	DENTED	148.00	65.00
1	GEAR PEDAL (CONSISTENT)	BENT	155.00	98.00
1	SET REAR SIGNALS (CONSISTENT)	CUT	100.00	100.00
1	REAR SEAT (CONSISTENT)	TORN	258.00	120.00
1	EXHAUST ASSY (CONSISTENT)	BENT	1,580.00	580.00
1	EXHAUST PROTECTOR (CONSISTENT)	CRACKED	150.00	150.00
1	EXHAUST END COVER (CONSISTENT)	CRACKED	45.00	45.00
2	REAR FAIRING (CONSISTENT)	BROKEN	680.00	410.00

Report Ref No. CS/ASM22005718/Tncm4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CENTER COVER (CONSISTENT)	CUT	220.00	120.00
1	SET REAR FOOTREST (CONSISTENT)	DENTED	170.00	120.00
1	SET REAR FOOTRST BRACKET (CONSISTENT)	NOT NECESSARY	310.00	-
1	REAR TAIL LAMP (CONSISTENT)	CRACKED	420.00	200.00
	LESS 10% DISCOUNT		-1,162.30	-487.80
			10,460.70	4,390.20
2	FORK INNER TUBES (SN) (CONSISTENT) }	SHIFTED	480.00	120.00
2	FORK OUTER TUBER (SN) (CONSISTENT) }	SHIFTED	520.00	-
1	FORK UNDER BRACKET (SN) (CONSISTENT) }	SHIFTED	265.00	-
	LESS 10% DISCOUNT		-126.50	-
			1,138.50	120.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
2	FORK OILS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN) (CONSISTENT)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN) (CONSISTENT)	NECESSARY	95.00	95.00
1	E.R.P. IU (SN) (CONSISTENT)	CUT	180.00	180.00
1	SET FAIRING COVER STICKET (SN) (CONSISTENT)	CRACKED	800.00	200.00
			1,199.00	561.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TOWING (LOD) S\$50.00 (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	30.00
	TO RESPRAY PAINTING.		680.00	350.00
	TO PROVIDE BODY FRAME REPAIR.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FUEL TANK.		520.00	300.00
			1,760.00	680.00
	<b>GRAND TOTAL</b>		<b>14,558.20</b>	<b>5,751.20</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,600.00</b>
---	--	--	-----------------

Report Ref No. CS/ASM22005718/Tncm4

**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**