

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005726/TVY3Q2**Date:** 11/08/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00013932204
Claimant Vehicle No :	SMZ5330Z	Insured Vehicle No :	GBA7561Y
Date of Loss:	09/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204086/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ5330Z	Engine No:	L15B4022665
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11102665
Reg. Date:	01/10/2015 (Man. Year: 2015)	Odometer:	110664 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,243.96	1,788.08	5,455.88	75.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,300.00	2,540.00	66.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,083.96	3,088.08	7,995.88	72.14
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	11,083.96	2,450.00	8,633.96	77.90
+ GST 7.00/7.00% (S\$)	775.88	171.50	604.38	77.90
Nett Amount (S\$)	11,859.84	2,621.50	9,238.34	77.90

INSPECTION

Date of Assignment:	21/06/2022	
Date Inspected:	17/06/2022	Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ5330Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	963.50 FL	*760.00 FL
2	1		*REAR BUMPER BRACKET LH	Not Necessary	53.50 FL	*- FL
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	156.00 FL	*- FL
4	1		*REAR SIDE BUMPER LH	Repair	325.10 FL	*- FL
5	1		*REAR TAILGATE	Bent	1,200.50 FL	*997.30 FL
6	1		*REAR TAILGATE INNER BOARD	Not Necessary	435.00 FL	*- FL
7	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	65.00 FL	*65.00 FL
8	1		*REAR TAILGATE LOGO	Necessary	55.00 FL	*55.00 FL
9	1		*REAR TAILGATE LOCK	Not Necessary	198.50 FL	*- FL
10	1		*REAR TAILGATE REFLECTOR LH	Cracked	245.30 FL	*245.30 FL
11	1		*REAR TAILGATE HINGES LH	Not Necessary	65.00 FL	*- FL
12	1		*REAR TAILGATE HINGES RH	Not Necessary	65.00 FL	*- FL
13	1		*REAR TAILLAMP LH	Not Necessary	550.00 FL	*- FL
14	1		*REAR TAILLAMP LOWER PANEL LH	Not Necessary	335.00 FL	*- FL
15	1		*REAR END PANEL	Repair	530.70 FL	*- FL
16	1		*REAR END PANEL INNER GARNISH	Not Necessary	153.70 FL	*- FL
17	1		*REAR FENDER LH	Not Necessary	950.90 FL	*- FL
18	1		*REAR FENDER INNER TRIM BOARD LH	Not Necessary	570.00 FL	*- FL
19	1		*REAR SPARE TYRE COMPARTMENT	Not Necessary	1,130.00 FL	*- FL
20	1		*REAR TAILGATE RUBBER	Not Necessary	170.00 FL	*- FL
21	1		*REAR SMART KEYLESS SENSOR	Not Necessary	268.50 FL	*- FL
22	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
23	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
24	1		*SET REAR BUMPER SENSORS	Not Necessary	260.00 FS	*- FS
25	1		*SET REAR TAILGATE INNER BOARD CLIPS	Not Necessary	45.00 FS	*- FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,941.20	2,212.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,697.24	424.52
Total Parts (\$)	7,243.96	1,788.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS REPLACE DAMAGED PARTS	New	50.00	30.00
2	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	100.00	0.00
3	TO TRANSFER REAR TAILGATE	New	80.00	60.00
4	TO DISMANTLE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
5	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	30.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER	New	1,800.00	500.00
7	TO CARRY -OUT BODY CAVITY PRESERVATION	New	50.00	30.00
8	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANLS FOR RUST PROTECTION	New	60.00	30.00
9	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,500.00	500.00
			Gross Labour Cost (\$)	3,840.00
				1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >