

ASS. REC. BY:

Taufik

REF:

CS/CT/2005726/Toy3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: GBA 7561YPolicy No. DMCVSNW00013932204Claims No. SNM22D204086/C02

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 947K.

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS W.P.

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMZ53307Yr Regn: 2015Oct.Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda VezelC.C. 1496Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 110664

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 2U11102665\*Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17R: ~ ~BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 9/6/2022D.O.I. 17/6/22Survey held at Yew Tee Auto WL.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/8/22 LS \$2450 confirmed by email (Red 8633.96, 77%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) 5/8/22-typistAdd Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Rep. Format: MerimenLump Sum / L.B. / \$ \$2450

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

**INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD****PARTICULARS OF CLAIM**

|                   |                     |                          |                |
|-------------------|---------------------|--------------------------|----------------|
| Claim Type:       | TP                  | Ref. No:                 |                |
| Policy No:        | 5122054401-01       | Date of Loss:            | 09/06/2022     |
| Vehicle Reg. No.: | <b>SMZ5330Z</b>     | Driveable?               | no             |
| Driver Age:       |                     | Third Party Vehicle No.: | GBA7561Y       |
| Any Injuries?     | no                  | Contact No:              | 82184032       |
| Insured/Claimant: | NG LIN LI, LORRAINE | Driver:                  | TRAN QUANG HUY |

**PARTS MODEL**

|                 |                    |                              |            |
|-----------------|--------------------|------------------------------|------------|
| Make/Model:     | Honda, Vezel - RU1 | Vehicle Reg. Date:           | 01/10/2015 |
| Vehicle Colour: |                    | Engine Number:               |            |
| Chassis No:     | RU11102665         | Odometer:                    |            |
| Total Loss?     |                    | Est. Duration of Repair(Day) |            |

**DESCRIPTION OF ACCIDENT/LOSS**

Description of Accident/loss CHAIN COLLISION  
 Remarks:  
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

**COST OF CLAIMS**

|                          | Amount           |
|--------------------------|------------------|
| Parts                    | 6,788.96         |
| Miscellaneous Items      | 455.00           |
| Labour                   | 2,230.00         |
| Paintwork Labour         | 1,610.00         |
| Towing                   | 0.00             |
| <b>Gross Total(S\$):</b> | <b>11,083.96</b> |
| <b>GST 7.00%(S\$):</b>   | <b>775.88</b>    |
| <b>Nett Amount(S\$):</b> | <b>11,859.84</b> |

This claim is handled by: Sky Toh T C

**REPAIR DETAILS****Estimates On Parts**

| No. | Qty | Particulars                        | Amount                    | %Disc  | After Disc                                           |
|-----|-----|------------------------------------|---------------------------|--------|------------------------------------------------------|
| 1   | 1   | REAR BUMPER <i>dismantle photo</i> | 963.50                    | -20.00 | 770.80 <i>de</i>                                     |
| 2   | 1   | REAR BUMPER BRACKET LH             | 53.50                     | -20.00 | 42.80 <i>x nn</i>                                    |
| 3   | 1   | REAR BUMPER REFLECTOR LH           | 156.00                    | -20.00 | 124.80 <i>x nn</i>                                   |
| 4   | 1   | REAR SIDE BUMPER LH                | 325.10                    | -20.00 | 260.08 <i>Rp</i>                                     |
| 5   | 1   | REAR TAILGATE                      | 1,200.50                  | -20.00 | 960.40 <i>67</i>                                     |
| 6   | 1   | REAR TAILGATE INNER BOARD          | 435.00                    | -20.00 | 348.00 <i>x nn</i>                                   |
| 7   | 1   | REAR TAILGATE VEZEL EMBLEM         | 65.00                     | -20.00 | 52.00 <i>de</i>                                      |
| 8   | 1   | REAR TAILGATE LOGO                 | 55.00                     | -20.00 | 44.00 <i>de</i>                                      |
| 9   | 1   | REAR TAILGATE LOCK                 | 198.50                    | -20.00 | 158.80 <i>x</i>                                      |
| 10  | 1   | REAR TAILGATE REFLECTOR LH         | 245.30                    | -20.00 | 196.24 <i>2 cur</i>                                  |
| 11  | 1   | REAR TAILGATE HINGES LH            | 65.00                     | -20.00 | 52.00 <i>x nn</i>                                    |
| 12  | 1   | REAR TAILGATE HINGES RH            | 65.00                     | -20.00 | 52.00 <i>x nn</i>                                    |
| 13  | 1   | REAR TAILLAMP LH                   | 550.00                    | -20.00 | 440.00 <i>x nn</i>                                   |
| 14  | 1   | REAR TAILLAMP LOWER PANEL LH       | 335.00                    | -20.00 | 268.00 <i>x nn</i>                                   |
| 15  | 1   | REAR END PANEL                     | 530.70                    | -20.00 | 424.56 <i>x nn</i>                                   |
| 16  | 1   | REAR END PANEL INNER GARNISH       | 153.70                    | -20.00 | 122.96 <i>x nn</i>                                   |
| 17  | 1   | REAR FENDER LH                     | 950.90                    | -20.00 | 760.72 <i>x nn</i>                                   |
| 18  | 1   | REAR FENDER INNER TRIM BOARD LH    | 570.00                    | -20.00 | 456.00 <i>x nn</i>                                   |
| 19  | 1   | REAR SPARE TYRE COMPARTMENT        | 1,130.00                  | -20.00 | 904.00 <i>x nn</i>                                   |
| 20  | 1   | REAR TAILGATE RUBBER               | 170.00                    | -20.00 | 136.00 <i>x nn</i>                                   |
| 21  | 1   | REAR SMART KEYLESS SENSOR          | 268.50                    | -20.00 | 214.80 <i>x nn</i>                                   |
|     |     |                                    | <b>Total Parts (\$\$)</b> |        | <b>6,788.96</b> <i>2122.60</i><br><i>20% 1698.08</i> |

**Estimates of Miscellaneous Items**

| No. | Qty | Particulars                             | Amount                  | %Disc | After Disc               |
|-----|-----|-----------------------------------------|-------------------------|-------|--------------------------|
| 1   | 1   | REAR NUMBER PLATE                       | 45.00                   | 0.00  | 45.00 <i>x nn</i>        |
| 2   | 1   | REAR BUMPER CLIPS (1 SET)               | 45.00                   | 0.00  | 45.00 <i>30</i>          |
| 3   | 1   | REAR BUMPER SENSORS (1 SET)             | 260.00                  | 0.00  | 260.00 <i>200 x nn</i>   |
| 4   | 1   | REAR TAILGATE INNER BOARD CLIPS (1 SET) | 45.00                   | 0.00  | 45.00 <i>x nn</i>        |
| 5   | 1   | REAR WINDSCREEN SEALANT                 | 60.00                   | 0.00  | 60.00 <i>rel</i>         |
|     |     |                                         | <b>Sub Total (\$\$)</b> |       | <b>455.00</b> <i>890</i> |

**Estimates On Labour**

| No. | Qty | Particulars                                                                                                                                                                    | Amount   | %Disc | After Disc                  |
|-----|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------|-----------------------------|
| 1   | 1   | To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.                                                                             | 50.00    | 0.00  | 50.00 <i>30</i>             |
| 2   | 1   | To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.                                                                        | 100.00   | 0.00  | 100.00 <i>50 x nn photo</i> |
| 3   | 1   | To Transfer Rear Tailgate.                                                                                                                                                     | 80.00    | 0.00  | 80.00 <i>60</i>             |
| 4   | 1   | To Dismantle and Refit Rear Windscreen Glass.                                                                                                                                  | 120.00   | 0.00  | 120.00 <i>✓</i>             |
| 5   | 1   | To Remove and Refit Rear Bumper Sensor.                                                                                                                                        | 80.00    | 0.00  | 80.00 <i>30</i>             |
| 6   | 1   | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power | 1,800.00 | 0.00  | 1,800.00 <i>500</i>         |

**Estimates On Labour**

| No.                      | Qty | Particulars | Amount | %Disc | After Disc |
|--------------------------|-----|-------------|--------|-------|------------|
|                          |     | tools.      |        |       |            |
| Gross Labour Cost (\$\$) |     |             |        |       | 2,230.00   |

**Estimates On Paint Work Labour**

| No.                      | Qty | Particulars                                                                                                                                                                                              | Amount   | %Disc | After Disc |
|--------------------------|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------|------------|
| 1                        | 1   | To Carry-Out Body Cavity Preservation.                                                                                                                                                                   | 50.00    | 0.00  | 50.00      |
| 2                        | 1   | To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.                                                                                                                           | 60.00    | 0.00  | 60.00      |
| 3                        | 1   | To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available. | 1,500.00 | 0.00  | 1,500.00   |
| Gross Labour Cost (\$\$) |     |                                                                                                                                                                                                          |          |       | 1,610.00   |

&lt; END OF ESTIMATES &gt;

1698.08

90

1300

3088.08

41842450

4days #

Taufik 97495747 / 62563561

'wp' 17/6/22 @ 1140

= 4 days

taufik@lkhamp.com

L/S Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: