

ASS. REC. BY: Taujiah

REF: CS/CT/2005726/Toy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMZ53307 Yr Regn: 2015 Oct.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel C.C. 1496
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 110604 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11102665*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/55R17
 R: ~ ~
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

 Bal. or Market Value: 947K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS w/p
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>17/6/22</u>

Survey held at Yew Tee Auto WL.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Lump Sum / I.B.L. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5122054401-01	Date of Loss:	09/06/2022
Vehicle Reg. No.:	SMZ5330Z	Driveable?	no
Driver Age:		Third Party Vehicle No.:	GBA7561Y
Any Injuries?	no	Contact No:	82184032
Insured/Claimant:	NG LIN LI, LORRAINE	Driver:	TRAN QUANG HUY

PARTS MODEL

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	01/10/2015
Vehicle Colour:		Engine Number:	
Chassis No:	RU11102665	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss CHAIN COLLISION
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	6,788.96
Miscellaneous Items	455.00
Labour	2,230.00
Paintwork Labour	1,610.00
Towing	0.00
Gross Total(S\$):	11,083.96
GST 7.00%(S\$):	775.88
Nett Amount(S\$):	11,859.84

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>dismantle photo</i>	963.50	-20.00	770.80 <i>de</i>
2	1	REAR BUMPER BRACKET LH	53.50	-20.00	42.80 <i>X un</i>
3	1	REAR BUMPER REFLECTOR LH	156.00	-20.00	124.80 <i>X un</i>
4	1	REAR SIDE BUMPER LH	325.10	-20.00	260.08 <i>Rp</i>
5	1	REAR TAILGATE	1,200.50	-20.00	960.40 <i>bt</i>
6	1	REAR TAILGATE INNER BOARD	435.00	-20.00	348.00 <i>X un</i>
7	1	REAR TAILGATE VEZEL EMBLEM	65.00	-20.00	52.00 <i>de</i>
8	1	REAR TAILGATE LOGO	55.00	-20.00	44.00 <i>de</i>
9	1	REAR TAILGATE LOCK	198.50	-20.00	158.80 <i>X</i>
10	1	REAR TAILGATE REFLECTOR LH	245.30	-20.00	196.24 <i>X un</i>
11	1	REAR TAILGATE HINGES LH	65.00	-20.00	52.00 <i>X un</i>
12	1	REAR TAILGATE HINGES RH	65.00	-20.00	52.00 <i>X un</i>
13	1	REAR TAILLAMP LH	550.00	-20.00	440.00 <i>X un</i>
14	1	REAR TAILLAMP LOWER PANEL LH	335.00	-20.00	268.00 <i>X un</i>
15	1	REAR END PANEL	530.70	-20.00	424.56 <i>X un</i>
16	1	REAR END PANEL INNER GARNISH	153.70	-20.00	122.96 <i>X un</i>
17	1	REAR FENDER LH	950.90	-20.00	760.72 <i>X un</i>
18	1	REAR FENDER INNER TRIM BOARD LH	570.00	-20.00	456.00 <i>X un</i>
19	1	REAR SPARE TYRE COMPARTMENT	1,130.00	-20.00	904.00 <i>X un</i>
20	1	REAR TAILGATE RUBBER	170.00	-20.00	136.00 <i>X un</i>
21	1	REAR SMART KEYLESS SENSOR	268.50	-20.00	214.80 <i>X un</i>
			Total Parts (\$\$)		6,788.96 <i>2122.60</i> <i>207.1698.08</i>

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE	45.00	0.00	45.00 <i>X un</i>
2	1	REAR BUMPER CLIPS (1 SET)	45.00	0.00	45.00 <i>30</i>
3	1	REAR BUMPER SENSORS (1 SET)	260.00	0.00	260.00 <i>200 X un</i>
4	1	REAR TAILGATE INNER BOARD CLIPS (1 SET)	45.00	0.00	45.00 <i>X un</i>
5	1	REAR WINDSCREEN SEALANT	60.00	0.00	60.00 <i>rel</i>
			Sub Total (\$\$)		455.00 <i>890</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 <i>30</i>
2	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 <i>50 X un photo</i>
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 <i>60</i>
4	1	To Dismantle and Refit Rear Windscreen Glass.	120.00	0.00	120.00 <i>✓</i>
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>30</i>
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power	1,800.00	0.00	1,800.00 <i>500</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		tools.			
Gross Labour Cost (\$\$)					2,230.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	0.00	50.00 30
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00 30
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,500.00	0.00	1,500.00 500 1300
Gross Labour Cost (\$\$)					1,610.00

< END OF ESTIMATES >

1698.08
 90
 1300

 3088.08
 41842450
 4 days #

Taufik 97495747 / 62563561
 'wp' 17/6/22 @ 1140
 = 4 days
 Taufik @ tkamp.com
 L/S Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: