



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### OPINION ON REPAIR COST FOR VEHICLE NO. COLUMN GUARD RAILING

Qty	Description of Parts	Condition	Recommended (\$)
	<b>LABOUR</b>		
	SUPPLY LABOUR, MATERIAL AND TRANSPORTATION TO REPLACE ONE NO OF DAMAGED COLUMN PROTECTION RAILING COMPLETE WITH YELLOW COLOUR PAINTING.		550.00
	SUPPLY LABOUR, MATERIAL AND TRANSPORTATION TO MAKE GOOD COLUMN PLASTERING AND TOUCH UP PAINTING.		400.00
			950.00
	<b>GRAND TOTAL</b>		<b>950.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>950.00</b>
------------------------------------	---------------

Report Ref No. CS1/LPM22005727/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.