

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 19/20/21/VC11/326231 Date: 22nd Jun 2022

Our Ref: CS1/LPM22005727/Eqy3e2

M/s Lonpac Insurance Bhd

21St Flr, Bangunan Public Bank No. 6 Jalan Sultan Sulaiman 50000 Kuala Lumpur, Malaysia (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: COLUMN GUARD RAILING

INSURED VEHICLE: BKW 6975 ACCIDENT DATE: 09/12/2020

We thank you for your instruction on 15/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of COLUMN GUARD RAILING from M/s Lu Yuan Construction Pte Ltd.
- b) Police Report of Vehicles BKW 6975.
- c) Colour damaged photographs of COLUMN GUARD RAILING.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : COLUMN GUARD RAILING

Make & Model : Year of Registration : Chassis Number : Engine Capacity : -



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

- 2. Our finding is that the repair cost of \$950.00 (before GST) quoted by M/s Lu Yuan Construction Pte Ltd is fair & reasonable.
- 3. We recommend that the repairs of the entire damage require about <u>2 (Two)</u> working days to complete.

Vehicle Inspected By:

la.

CHEN TSUE YEE Automotive Assessor



ANG BRYAN TANI Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.