

SPF ACCIDENT CLAIMS SECTION
1 Logistics Services Executive
Police Logistics Base
1 Hemmant Road
Singapore 438675



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

DAMAGE ASSESSMENT REPORT

www.vicom.com.sg
Company Registration No: 198100320K

GENERAL INFORMATION			
VAC Ref. No.	: 560621	Claim No.	: ACS/105/009/2020/036
Accident Date	: 27/07/2020	Claim Type	: THIRD PARTY
Assignment Date	: 04/08/2020	Policy No.	:
Survey Date	: 04/08/2020		
Report Date	: 19/08/2020		

VEHICLE PARTICULARS			
Vehicle No.	: SMH8480Z	Chassis No.	: GB71086395
Registration Date	: 12/02/2019	Engine No.	: LEB5624179
Make	: HONDA	Engine Cap.	: 1496 CC
Model	: FREED HYBRID 1.5G AU	Transmission	: AUTOMATIC
		Colour	: SILVER

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 138026		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	185/65 R15	DUNLOP	6
FRONT LH	185/65 R15	DUNLOP	6
REAR RH	185/65 R15	DUNLOP	6
REAR LH	185/65 R15	DUNLOP	6

SURVEY CONDUCTED AT	
365 AUTOMOTIVE 25 K BT RD 4 #01-55 SYNERGY @ KB SP 417800 PEIJIE: 91690825 IT WOULD REQUIRE AN ESTIMATED 7 DAYS REPAIR PERIOD	

REMARKS
[1]Workshop did not give repair estimate.
[2]This survey was carried out on without prejudice basis.
[3]Estimate Cost Range : Lower - [5000.00] Higher - [8000.00]
[4]Nothing herein should be construed as an admission or acceptance of liability in any way on our part.All of the Government's rights are expressly reserved.

DAMAGE ASSESSMENT REPORT**Annex A: List of damaged parts**

#	Qty	Vehicle Parts Description	Condition
1	1	Bonnet	Repair
2	1	Bonnet Hinges (Lh&Rh)	Bent
3	1	Front Bumper	Deformed
4	1	Front Bumper Bracket (Lh&Rh)	Broken
5	1	Front Bumper Side Retainer (Lh&Rh)	Cracked
6	1	Front Bumper Grille	Cracked
7	1	Front Bumper Grille Chrome	Cracked
8	1	Front Bumper Tow Cover	Broken
9	1	Front Number Plate With Bracket	Dent
10	1	Front Bumper Lower Grille	Intact
11	1	Front Head Lamp (Lh)	Intact
12	1	Front Head Lamp (Rh)	Grazed
13	1	Front Fender (Lh)	Intact
14	1	Front Fender (Rh)	Repair
15	1	Front Fender Inner Shield (Lh&Rh)	Intact
16	1	Front Bumper Reinforcement	Dent
17	1	Front Support Panel	Intact
18	1	Bonnet Lock Assy	Intact
19	1	Radiator	Intact
20	1	Condenser	Intact
21	1	Engine Under Cover	Intact
22	1	Tailgate	Buckled
23	1	Tailgate Damper (Lh&Rh)	Working Condition
24	1	Tailgate Reflector (Lh&Rh)	No Damage
25	1	Tailgate Outer Garnish Chrome	No Damage
26	1	Rear Number Plate With Bracket	Intact
27	1	Rear Number Plate Lamp (Lh&Rh)	Working Condition
28	1	Reverse Camera	Working Condition
29	1	Reverse Sensor	Malfunction
30	1	Tailgate Inner Board	Intact
31	1	Tailgate Lock Assembly	Intact
32	1	Tailgate Inner Handle Holder	Cracked
33	1	Rear Bumper	Deformed
34	1	Rear Bumper Bracket (Lh&Rh)	Broken
35	1	Rear Bumper Side Retainer (Lh)	Intact
36	1	Rear Bumper Side Retainer (Rh)	Cracked
37	1	Rear Bumper Tow Cover (Rh)	Grazed
38	1	Rear Bumper Reflector (Lh&Rh)	Intact
39	1	Rear End Panel Top Garnish	Distorted
40	1	Rear End Panel	Dent
41	1	Tail Lamp (Lh&Rh)	Intact
42	1	Exhaust Pipe Assembly	Intact

DAMAGE ASSESSMENT REPORT**Annex B: Comments****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained front & rear portion damage.

The damages seen during our survey were bonnet, front / rear bumper , tailgate, head lamp (rh) and surrounding areas. A fuller detailed description of the damages is in Annex A of this damage assessment report.

We enclose 182 photographs of this vehicle taken during our attendance.

The repair estimate was not available during our survey attendance.

This Vehicle has :

a) estimated pre-accident value = S\$84,800.00

b) estimated salvage value = S\$42,857.00

c) economical repair value = S\$41,943.00

Although this vehicle was registered on 12/02/2019, a relatively brand new vehicle, we explore repairs on lump-sum basis with the workshop.

Joseph Che Yong Seng
for VICOM Ltd