

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005729/DPA3Q2**Date:** 15/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700033462
Claimant Vehicle No :	SMT4265S	Insured Vehicle No :	SLQ9872J
Date of Loss:	06/06/2022	Nature of Claim:	TP
		Claim No:	5903696187SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT4265S	Engine No:	3A92UJB1374
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH003331
Reg. Date:	11/06/2020 (Man. Year: 2019)	Odometer:	37014 km
Colour:	Blue		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,055.00	4,071.66	4,983.34	55.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,760.00	1,950.00	52.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,765.00	5,831.66	6,933.34	54.32
Approved Total (Overridden) (S\$)		4,650.00		
Nett Amount (S\$)	12,765.00	4,650.00	8,115.00	63.57
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,299.45		
Global Sum Settlement (S\$)		5,250.00		

INSPECTION

Date of Assignment:	08/06/2022	Alfred Auto Services & Supplies (HQ)
Date Inspected:	08/06/2022 Inspected At:	Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2
Estimated Period of Repair:	5.0 days	Singapore 569538

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	799.00 F	*799.00 FL
2	1		*REAR BOOT SPOILER	Not Necessary	503.00 F	*- FL
3	2		*REAR BOOT HINGER	Not Necessary	380.00 F	*- FL
4	1		*REAR BOOT CHROME	Mtg Cracked	328.00 F	*328.00 FL
5	1		*REAR BOOT LOGO	Necessary	49.00 F	*49.00 FL
6	1		*ATTRAGE EMBLEM	Necessary	38.00 F	*38.00 FL
7	1		*MIVEE EMBLEM	Necessary	38.00 F	*38.00 FL
8	1		*CYCLE LOGO	Necessary	20.00 F	*20.00 FL
9	1		*REAR BOOT LOCK	Bent / Damaged	216.00 F	*165.00 FL
10	1		*REAR WEATHER SLIP	Deformed	178.00 F	*155.00 FL
11	1		*REAR END PANEL	Dented	550.00 F	*525.00 FL
12	2		*REAR LAMP	Cracked / Mtg Cracked	596.00 F	*596.00 FL
13	2		*REAR LAMP PANEL	Not Necessary	382.00 F	*- FL
14	1		*REAR BUMPER	Dented	759.00 F	*660.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Mtg Broken	100.00 F	*60.00 FL
16	2		*REAR BUMPER CORNER GARNISH	Not Necessary	62.00 F	*- FL
17	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
18	1		*REAR BUMPER LOCK SPOILER	Dented	799.00 F	*600.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Not fitted	399.00 F	*- FL
20	1		*SET REAR PARKING SENSOR	Damaged	385.00 FS	*220.00 FS
21	1		*SPARE TYRE BOARD	Not Necessary	611.00 F	*- FL
22	1		*REAR RH FENDER	Repair	785.00 F	*- FL
23	1		*REAR RH FENDER AIR DUCT	Not Necessary	59.00 F	*- FL
24	1		*REAR PANEL GARNISH	Mtg Deformed	295.00 F	*186.40 FL
25	1		*REAR NO PLATE LAMP (1 PCS Not Necessary)	1 PCS Mtg Broken	76.00 F	*38.00 FL
26	1		*REAR NO PLATE & BOX	Not Necessary	60.00 F	*- FL
27	1		*REAR CAMERA	Not Necessary	399.00 F	*- FL
28	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	59.00 F	*- FL
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,055.00	4,497.40
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	425.74
Total Parts (\$)	9,055.00	4,071.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT WIRING & CHECK WIRING FOR ALL LIGHTING & INSTALL PARKING SENSOR	New	180.00	40.00
2	TO REMOVE & REFIT INTERIOR GARNISH ,CARPET & ALL ACCIDENT AFFECTED AREA	New	180.00	80.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	180.00	0.00
4	TO KNOCKING ,WELDING ,STRAIGHTENING ,REPAIR & RENEW ALL ACCIDENT DAMAGE PARTS	New	1,300.00	800.00
5	TO RESPRAY PAINTING ON ALL ACCIDENT INNER ,OUTER ACCIDENT AFFECTED AREA	New	1,600.00	800.00
6	TO RUST PROOF ALL ACCIDENT DAMAGED AFFECTED AREA	New	120.00	40.00
7	TO REMOVE & REFIT RENEW REAR EXHAUST	New	150.00	0.00
Gross Labour Cost (\$\$)			3,710.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >